ANOKA COUNTY

COUNTY DITCH INSPECTION REPORT

DITCH # 28

DATE: 7/12/94

BY: PK Ruud

COMMUNITIES: East Bethel, Ham Lake

REMARKS:

Driveway Entrance to "Antiques of Meadowmoor". Ditch well defined and

flowing. From here north to CSAH # 22, the ditch follows the east

ditch of TH 65.

Briarwood At this crossing, 1/8 mile east of TH 65, the ditch is well defined

and flowing. Considerable sand and gravel have washed off the

road into the ditch.

TH #65 At this north crossing, the ditch is well defined and flowing slowly.

Several trees lying across the ditch to the east.

TH # 65 At this south crossing, the ditch from the east is well defined. A

beaver dam exists about 100' east of the r/w line. No apparent flow

from the east.

W. Service Rd. At this north crossing, the ditch is well defined. No apparent flow.

W. Service Rd. At this south crossing, the ditch is defined. No apparent flow.

Briarwood At this crossing, about 3/4 mile east of TH 65, the ditch is defined

on the south side, but overgrown with brush. No apparent flow.

ACTIVITIES:

The east ditch along TH 65, between the two crossings in the NW1/4 Of Section 5, has become the active route of the ditch. This, in reality, replaces the loop that crossed the highway to the west side and then crossed back to the east side.

The County Board, in response to a petition for a ditch repair, ordered an Engineer's report for this ditch in about 1988. See the ditch file for details.

ANOKA COUNTY

COUNTY DITCH INSPECTION REPORT

DITCH # 28 (Cont'd.)

DATE: 7/28/94

BY: PK Ruud

COMMUNITIES: East Bethel, Ham Lake

REMARKS:

Following a review of the ditch records covering the ditch repair that was done in 1920, the following additional crossings were viewed:

Swedish Drive

Marshy area on both sides of the road. Ditch not defined.

Deerwood Lane

Ditch well defined but overgrown with grass away from the street.

No apparent flow.

187th Lane

Ditch defined and flowing.

Buchanan Street

Ditch defined and flowing.

Fillmore Street

Ditch defined and clear of brush. No apparent flow.

ACTIVITIES:

As a part of the designation of the ditch system at the time of the 1920 repair, the ditches on both the east and west sides of TH 65 became parts of the Ditch 28 system.

