

CULVERT NUMBER:

12A - OK

SIDE OF CULVERT: SW
(N, S, E, W)

SIDE OF CULVERT: NE
(N, S, E, W)

PIPE SIZE: 42"

PIPE LENGTH: 57'

PIPE TYPE: CMP

PIPE INVERT: 898.72
(ELEVATION)

PIPE INVERT: 897.26
(ELEVATION)

PIPE CONDITION: GOOD

PIPE CONDITION: GOOD

WEIR: (SHOOT)
(Y/N)

WEIR: (SHOOT)
(Y/N)

WATER ELEVATION: 899.29

WATER ELEVATION: 899.29

FLOW DIRECTION: EAST

FLOW DIRECTION: EAST

ROAD ELEVATION: 903.52

ROAD ELEVATION: 904.48

LIST OF MAINTENANCE ACTIVITIES THAT IS VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE: NO VISIBLE DAMAGE

- TALKED TO GARY HOULE - SAID THIS PIPE WAS AN OVER FLOW - EXISTING PIPE NOT FUNCTIONING SHOT EXISTING PIPE AS 12-1A

NOTES: - SW SIDE OF PIPE VERY HIGH COMPARED TO NE SIDE