

CULVERT NUMBER: 12-2A ← This should be 12B

SIDE OF CULVERT: SW
(N, S, E, W)

SIDE OF CULVERT: NE
(N, S, E, W)

PIPE SIZE: 48"

PIPE LENGTH: 49.5'

PIPE TYPE: CMP

PIPE INVERT: 896.58
(ELEVATION)

PIPE INVERT: 896.53
(ELEVATION)

PIPE CONDITION: BENT

PIPE CONDITION: OK

WEIR: (SHOOT) _____
(Y/N)

WEIR: (SHOOT) _____
(Y/N)

WATER ELEVATION: 899.29

WATER ELEVATION: 899.29

FLOW DIRECTION: EAST

FLOW DIRECTION: EAST

ROAD ELEVATION: 903.52

ROAD ELEVATION: 904.48

LIST OF MAINTENANCE ACTIVITIES THAT IS

VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE: MUCK = 899.69 @
SW END OF CULVERT - NEEDS TO BE EXCAVATED
TO FUNCTION PROPERLY - END IS BENT

NOTES: _____

