

CULVERT NUMBER:

POOL 1 CONTROL

This should be Culvert 5

SIDE OF CULVERT: W
(N, S, E, W)

SIDE OF CULVERT: E
(N, S, E, W)

PIPE SIZE: 48"

PIPE LENGTH: 25.0'

PIPE TYPE: CMP

PIPE INVERT: N/A
(ELEVATION)

PIPE INVERT: 895.37
(ELEVATION)

PIPE CONDITION: GOOD

PIPE CONDITION: GOOD

WEIR: (SHOOT) YES
(Y/N)

WEIR: (SHOOT) —
(Y/N)

WATER ELEVATION: 897.78

WATER ELEVATION: 897.78

FLOW DIRECTION: EAST

FLOW DIRECTION: EAST

ROAD ELEVATION: 901.16

ROAD ELEVATION: 900.51

LIST OF MAINTENANCE ACTIVITIES THAT IS VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE: NO VISIBLE DAMAGE

NOTES: 12.45 ON GUARD - GRATE IS SITTING ON TOP OF CONC. WEIR - W PIPE IS TUCKER UNDER 3' +/-, UNABLE TO GET INV. - EAST PIPE BOTTOM AT INVERT IS CUT AWAY, BACK 2-3 FT.