
11	VEF	T	11/1	IR.	/ID	CE	٠.
 JL	VEI	`	IVL	JIV		Er	١.



This should be Culvert 8

SIDE OF CULVERT: (N, S, E, W)	W	SIDE OF CULVERT: (N, S, E, W)	<u> </u>					
PIPE SIZE:	30 "	PIPE LENGTH:	521					
PIPE TYPE:	CMP							
PIPE INVERT: (ELEVATION)	885.78	PIPE INVERT: (ELEVATION)	885.19					
PIPE CONDITION:	UNSURE	PIPE CONDITION:	UNSURE					
WEIR: (SHOOT)	898.32	WEIR: (SHOOT)						
WATER ELEVATION:	886.57	WATER ELEVATION:	887.84					
FLOW DIRECTION:	EAST	FLOW DIRECTION:	EAST					
ROAD ELEVATION:	891.73	ROAD ELEVATION:	891.71					
LIST OF MAINTENANCE ACTIVITIES THAT IS VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE:								
NOTES: -BOTH PIPES UNDER WATER -NOT SURE THE								