

CULVERT NUMBER:

CULVERT 8 ??

New Culvert -  
Not part of  
County Ditch  
System ??

SIDE OF CULVERT: W  
(N, S, E, W)

SIDE OF CULVERT: E  
(N, S, E, W)

PIPE SIZE: 30"

PIPE LENGTH: 39'

PIPE TYPE: ~~CP~~ CMP

PIPE INVERT: 886.42  
(ELEVATION)

PIPE INVERT: 885.95  
(ELEVATION)

PIPE CONDITION: OK

PIPE CONDITION: BAD

WEIR: (SHOOT) 889.89  
(Y/N)

WEIR: (SHOOT) \_\_\_\_\_  
(Y/N)

WATER ELEVATION: 887.76

WATER ELEVATION: 887.69

FLOW DIRECTION: EAST

FLOW DIRECTION: EAST

ROAD ELEVATION: 892.09

ROAD ELEVATION: 892.11

LIST OF MAINTENANCE ACTIVITIES THAT IS  
VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE: SIDES (EAST) ARE  
DETERIORATING - CAN NOT STAND ON END OF PIPE

NOTES: - WATER ON W. SIDE WAS INSIDE WEIR - OUTSIDE  
OF WEIR WAS DRY