CULVERT NUMBER:

POOL 4 STRUCTURE of County Ditch System

SIDE OF CULVERT: (N, S, E, W)	<u></u>	SIDE OF CULVERT: (N, S, E, W)	<u> </u>
PIPE SIZE:	40"	PIPE LENGTH:	52'
PIPE TYPE:	CMP		
The state of the s			
PIPE INVERT: (ELEVATION)	891.60	PIPE INVERT: (ELEVATION)	890.30
PIPE CONDITION:	EXCELLENT	PIPE CONDITION:	EXCELLENT
WEIR: (SHOOT) 4 (Y)N)	70P TOP	WEIR: (SHOOT)	
WATER ELEVATION:	895.11	WATER ELEVATION:	889.65
FLOW DIRECTION:	EAST	FLOW DIRECTION:	EAST
ROAD ELEVATION:	<u>898.43</u>	ROAD ELEVATION:	898.18
LIST OF MAINTENANCE ACTIVITIES THAT IS VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE: NO VISIBLE DAMAGE - LOOKS LIKE NEW CONSTRUCTION /RE-CONSTRUCTION			
and the second s			
NOTES: BOAR	DS IN PLACE U	ENT SIDE	OFWEIR
W			
7			