

This is Culvert No 21, County Ditch No 35, Branch 5

CULVERT NUMBER:

POOL 10 PRIMARY

SIDE OF CULVERT: W
(N, S, E, W)
PIPE SIZE: 48"
PIPE TYPE: CMP

SIDE OF CULVERT: E
(N, S, E, W)
PIPE LENGTH: 46'

PIPE INVERT: 888.45
(ELEVATION)
PIPE CONDITION: GOOD
WEIR: (SHOOT) 891.53
(Y/N)
WATER ELEVATION: 892.07
FLOW DIRECTION: EAST
ROAD ELEVATION: 896.83

PIPE INVERT: 888.45
(ELEVATION)
PIPE CONDITION: DETERIORATING
WEIR: (SHOOT)
(Y/N)
WATER ELEVATION: 888.84
FLOW DIRECTION: EAST
ROAD ELEVATION: 897.13

LIST OF MAINTENANCE ACTIVITIES THAT IS VISIBLE AND NEEDS TO OCCUR ON THE STRUCTURE:
VP W. SIDE

BEAVER HAS DAMMED

NOTES: PIPE ON E. SIDE DETERIORATING ON LOWER SIDES,
3-4 FEET IN TO PIPE