HISTORY OF GOVERNMENT CORNER

County of Anoka

State of Minnesota

East 1/4 Corner of Sec. 11 Township 31 Range 24

CORNER HISTORY:

November 26, 1943 - H.A. Cartwright found concrete monument flush with the surface. Established ties to monument.

July 1955 - Minder Engineering Company found concrete monument and updated ties.

July 22, 1960 - Found concrete monument flush with the surface and updated ties. Iron pipe on north side of monument.

June 5, 1964 - Found concrete monument flush with the surface with iron pipe on the north side and updated ties.

June 1, 1965 - Found concrete monument flush with the surface with iron pipe on the north side and added additional ties prior to road construction.

September 12, 1966 - Set 1/2" iron pipe flush with surface after road construction using ties.

August 18, 1967 - Replaced 1/2" iron pipe with a cast iron monument. Updated ties.

July 24, 1970 - Found cast iron monument and updated ties.

July 8, 1974 - Found cast iron monument and updated ties.

June 20, 1977 - Found cast iron monument and updated ties.

October 29, 1978 - Found cast iron monument missing. Reset position of corner with P.K. nail using ties.

October 30, **1978 -** Replaced P.K. nail with a cast iron monument before blacktop construction set flush with the surface. Updated ties.

July 7, 1980 - Set P.K. nail in position of corner using ties.

December 30, 1981 - Found cast iron monument missing. Reset position of corner with P.K. nail using one tie and a traverse to the north and south. Updated ties.

August 19, 1983 - Replaced P.K.nail with a cast iron monument and set P.K. nails 2.00' south and east. Updated ties.

August 13, 1990 - Found cast iron monument and updated ties.

August 8, 1994 - Found cast iron monument and updated ties.

August 2, 2001 - Found cast iron monument and established NAD 1983 (1996 Adjustment) Anoka County Project Coordinates by Static GPS methods. Updated ties.

September 19, 2005 - Found cast iron monument and updated ties.

February 17, 2010 - Found cast iron monument flush with the surface and updated ties.