

DITCH #18

Names of the Owners of Lands that are Assessed for the Repair of said Ditch.	Description of Land to be Assessed	Sec.	Twp.	Range	No. of acres		Amount that each tract of land benefits	Amount pay for
					in each tract Ac. 100ths	benefited Ac. 100ths		
Clifford C. & Hazel L. Wyatt	SW $\frac{1}{4}$ of NW $\frac{1}{4}$	27	34	24	40	25	\$ 220.00	\$ 166.28
Merle Loran & Arlene D. Gaslin	NW $\frac{1}{4}$ of SW $\frac{1}{4}$	27	34	24	40	18	216.00	163.26
Merle Loran & Arlene D. Gaslin	NE $\frac{1}{4}$ of SE $\frac{1}{4}$	28	34	24	40	6	72.00	54.42
Merle Loran & Arlene D. Gaslin	Pt. of SE $\frac{1}{4}$ of SE $\frac{1}{4}$	28	34	24	40	35	420.00	317.44
Ole H. & Nicoline Hansen	SW $\frac{1}{4}$ of SW $\frac{1}{4}$	27	34	24	40	15	120.00	90.70
State of Minnesota, In Trust	NE $\frac{1}{4}$ of NE $\frac{1}{4}$	33	34	24	40	35	420.00	317.44
Lillian Vrooman	NW $\frac{1}{4}$ of NE $\frac{1}{4}$	33	34	24	40	12	96.00	72.56
Federal Land Bank of St. Paul	SW $\frac{1}{4}$ of SE $\frac{1}{4}$	28	34	24	40	5	40.00	30.23
Federal Land Bank of St. Paul	SE $\frac{1}{4}$ of SW $\frac{1}{4}$	28	34	24	40	25	200.00	151.16
State of Minnesota, In Trust	<del>NW<math>\frac{1}{4}</math> of NW<math>\frac{1}{4}</math> Pt. W<math>\frac{1}{2}</math> of NW<math>\frac{1}{4}</math>, Beg. at NE cor. of W<math>\frac{1}{2}</math> of NW<math>\frac{1}{4}</math> run- ing 20 rds. W., th. S. 80 rds, th. E. 20 rds., th. N. 80 rds. terminating at pt. of beg. Pt. W<math>\frac{1}{2}</math> of NW<math>\frac{1}{4}</math> SW<math>\frac{1}{4}</math> of NW<math>\frac{1}{4}</math></del>	34	34	24	<del>40</del> 10	12	144.00	108.84
State of Minnesota, In Trust	<del>Pt. W<math>\frac{1}{2}</math> of NW<math>\frac{1}{4}</math> SW<math>\frac{1}{4}</math> of NW<math>\frac{1}{4}</math></del>	34	34	24	<del>40</del> 10	12	144.00	108.84
<del>XXXXXX</del> Geo. P. & Anna Braastad <i>H. Braastad</i>	SE $\frac{1}{4}$ of NE $\frac{1}{4}$	33	34	24	40	30	360.00	272.09
George P. & Anna J. Braastad	W $\frac{1}{2}$ of NE $\frac{1}{4}$ of SE $\frac{1}{4}$	33	34	24	20	13	156.00	117.91
Anna C. Gilson	E $\frac{1}{2}$ of NE $\frac{1}{4}$ of SE $\frac{1}{4}$	33	34	24	20	18	216.00	163.26
Anna C. Gilson, et al	NW $\frac{1}{4}$ of SW $\frac{1}{4}$	34	34	24	40	8	96.00	72.56
George P. & Anna Braastad	W $\frac{1}{2}$ of SE $\frac{1}{4}$ of SE $\frac{1}{4}$	33	34	24	20	18	216.00	163.26
Anna C. Gilson	E $\frac{1}{2}$ of SE $\frac{1}{4}$ of SE $\frac{1}{4}$	33	34	24	20	8	96.00	72.56
George P. & Anna J. Braastad	NW $\frac{1}{4}$ of SE $\frac{1}{4}$	33	34	24	40	8	64.00	48.37
Anna C. Gilson, et al	SW $\frac{1}{4}$ of SW $\frac{1}{4}$	34	34	24	40	4	48.00	36.28

DITCH # 18

OWNER	SEC.	TWP.	R.	AMT. OF LIEN	1st INSTALLMENT		2nd INSTALLMENT		3rd INSTALLMENT		4th INSTALLMENT		5th INSTALLMENT	
					1949	INTEREST	1950	INTEREST	1951	INTEREST	1952	INTEREST	1953	INTEREST
SW 1/4 of NW 1/4	27	34	24	166 28	3325	221 36.46	3325	516 38.41	3325	399 37.24	3325	266 35.91	3328	1.33 34.61
NW 1/4 of SW 1/4	27	34	24	163 26	3265	217 34.82	3265	522 37.87	3265	392 36.57	3265	261 35.26	3266	1.31 33.97
NE 1/4 of SE 1/4	28	34	24	54 42	1088	72 11.60	1088	174 12.62	1088	1.31 12.19	1088	1175	1090	.44 11.34
Pt. of SE 1/4 of SE 1/4	28	34	24	317 44	6348	423 67.71	6348	1016 73.64	6348	7.62 71.10	6348	5.08 68.56	6352	2.54 66.06
SW 1/4 of SW 1/4	27	34	24	90 70	1814	121 19.36	1814	290 21.04	1814	2.18 20.32	1814	1.45 19.59	1814	.73 18.87
NE 1/4 of NE 1/4	33	34	24	317 44	6348	423 67.71	6348	1016 73.64	6348	7.62 71.10	6348	5.08 68.56	6352	2.54 66.06
NW 1/4 of NE 1/4	33	34	24	72 56	1451	97 15.48	1451	232 16.83	1451	1.74 16.25	1451	1.16 15.67	1452	.58 15.10
SW 1/4 of SE 1/4	28	34	24	30 23	604	40 6.44	604	97 7.01	604	.72 6.76	604	.48 6.52	607	.24 6.31
SE 1/4 of SW 1/4	28	34	24	151 16	3023	201 32.24	3023	484 35.07	3023	3.62 33.86	3023	2.42 32.65	3024	1.21 31.45
NW 1/4 of NW 1/4	34	34	24	108 84	2176	145 23.21	2176	348 25.24	2176	2.61 24.37	2176	1.74 23.50	2180	.87 22.67
SW 1/4 of NW 1/4	34	34	24	108 84	2176	145 23.21	2176	348 25.24	2176	2.61 24.37	2176	1.74 23.50	2180	.87 22.67
SE 1/4 of NE 1/4	33	34	24	272 09	5441	362 58.03	5441	871 63.12	5441	6.53 60.94	5441	4.35 58.76	5445	2.18 56.63
W 1/2 of NE 1/4 of SE 1/4	33	34	24	117 91	2358	157 25.15	2358	377 27.35	2358	2.83 26.41	2358	1.89 25.47	2359	.94 24.53
E 1/2 of NE 1/4 of SE 1/4	33	34	24	163 26	3265	217 34.82	3265	522 37.87	3265	3.92 36.57	3265	2.61 35.26	3266	1.31 33.97
NW 1/4 of SW 1/4	34	34	24	72 56	1451	97 15.48	1451	232 16.83	1451	1.74 16.25	1451	1.16 15.67	1452	.58 15.10
W 1/2 of SE 1/4 of SE 1/4	33	34	24	163 26	3265	217 34.82	3265	522 37.87	3265	3.92 36.57	3265	2.61 35.26	3266	1.31 33.97
E 1/2 of SE 1/4 of SE 1/4	33	34	24	72 56	1451	97 15.48	1451	232 16.83	1451	1.74 16.25	1451	1.16 15.67	1452	.58 15.10
NW 1/4 of SE 1/4	33	34	24	48 37	967	64 10.31	967	155 11.22	967	1.16 10.83	967	.77 10.44	969	.39 10.08
SW 1/4 of SW 1/4	34	34	24	36 28	725	48 7.73	725	116 8.41	725	.87 8.12	725	.58 7.83	728	.29 7.57
Bethel & St. Francis Rd. by Ditch #18 N. side of Highway				188 96	3779	252 40.31	3779	605 43.84	3779	4.53 42.32	3779	3.02 40.81	3780	1.51 39.31
Bethel & St. Francis Rd, by Ditch #18 S. side of Highway				188 96	3779	252 40.31	3779	605 43.84	3779	4.53 42.32	3779	3.02 40.81	3780	1.51 39.31
NE 1/4 of NE 1/4	4	33	24	272 10	5442	362 58.04	5442	871 63.13	5442	6.53 60.95	5442	4.35 58.77	5442	2.18 56.60
NW 1/4 of NE 1/4	4	33	24	317 44	6348	423 67.71	6348	1016 73.64	6348	7.62 71.10	6348	5.08 68.56	6352	2.54 66.06
SW 1/4 of NE 1/4	4	33	24	18 14	362	24 3.86	362	58 4.20	362	.43 4.02	362	.29 3.91	366	.15 3.81
NE 1/4 of NW 1/4	4	33	24	27 21	544	36 5.80	544	87 6.31	544	.65 6.09	544	.44 5.88	545	.22 5.67
SE 1/4 of NW 1/4	4	33	24	226 75	4535	302 48.37	4535	726 52.61	4535	5.44 50.79	4535	3.63 48.98	4535	1.81 47.16
SW 1/4 of NW 1/4	4	33	24	108 84	2176	145 23.21	2176	348 25.24	2176	2.61 24.37	2176	1.74 23.50	2180	.87 22.67
SE 1/4 of NE 1/4	5	33	24	9 07	181	12 1.93	181	29 2.10	181	.22 2.03	181	.14 1.95	183	.07 1.90
NW 1/4 of SW 1/4	4	33	24	45 35	907	60 9.67	907	145 10.52	907	1.09 10.16	907	.73 9.80	907	.36 9.43
				3930 28	78594	5233 838.27	78594	12560 911.54	78594	94.31 880.26	78594	63.84 848.80	78652	31.46 817.98

45.21

22 2000

9 8

Names of the Owners of Lands that are Assessed for the Repair of said Ditch	Description of Land to be Assessed	Sec.	Twp.	Range	No. of acres in each tract Ac. 100ths	No. of acres benefited Ac. 100ths	Amount that each tract of land benefits pay	Amount each tract must pay for repair of ditch
Anoka County Highway Dept.	Bethel & St. Francis Rd. by Ditch #18 N. side of Highway						250.00	188.96
Anoka County Highway Dept.	South side of Highway						250.00	188.96
Carl & Regina M. Arneson	NE $\frac{1}{4}$ of NE $\frac{1}{4}$	4	33	24	40	30	360.00	272.10
Walter C. Strommer	NW $\frac{1}{4}$ of NE $\frac{1}{4}$	4	33	24	40	35	420.00	317.44
Walter C. Strommer	SW $\frac{1}{4}$ of NE $\frac{1}{4}$	4	33	24	40	2	24.00	18.14
John Colline, et ux	NE $\frac{1}{4}$ of NW $\frac{1}{4}$	4	33	24	40	3	36.00	27.21
John Colline, et ux	SE $\frac{1}{4}$ of NW $\frac{1}{4}$	4	33	24	40	25	300.00	226.75
John & Bertha Colline	SW $\frac{1}{4}$ of NW $\frac{1}{4}$	4	33	24	40	12	144.00	108.84
Bertha Shadick	SE $\frac{1}{4}$ of NE $\frac{1}{4}$	5	33	24	40	1	12.00	9.07
Robert E. Leathers	NW $\frac{1}{4}$ of SW $\frac{1}{4}$	4	33	24	40	5	60.00	45.35
					1000	420	5200.00	3930.28