

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

No. 660.—Pioneer Press Co., St. Paul, Minn.

Filed Aug 31, 1893.

*G. W. Putnam,
L. Co. Auditor.*

[Faint handwritten notes and bleed-through from the reverse side of the page, including numbers and illegible text.]

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No. 21

SECTION	TIME WITHIN WHICH WORK MUST BE DONE	MANNER IN WHICH WORK MUST BE DONE	MATERIALS USED	COST OF MATERIALS AND WORK
State No. <u>D</u> to State No. <u>90</u>	July 1 st 1894	Work taken from ditch to the level close to ditch and loose material thrown to the ordinary level off		
Sta 90 to Sta 170	From 20 th June 1894	Ditches are about 3' bridge at 137 to 3m end of pin because 2 1/2 x 1 1/2 x 1/6 ft. long with 4 small log plungers, 8 ft. long and 10" diam water -		1000
Sta 170 to 240	From 1 st June 1894	The old ditches to be filled at upper end when car off, on lower end filled when when water 10 feet of new ditch. All angles to be rounded off with a very sharp as may be practical. - Slates are set for right hand edge of ditch		