

ANOKA COUNTY
COUNTY DITCH INSPECTION REPORT

DITCH # 27

DATE 7/19/94

BY: P K Ruud

COMMUNITIES: Burns, Ramsey


REMARKS:

CSAH # 5	Ditch well defined and flowing.
Xenolith St	Branch ditch is defined, no apparent flow. Pond excavated along the west side of the street. (See note below.)
CR #64	Ditch well defined and flowing.
CR # 163	Ditch well defined and flowing slowly.
CSAH # 22	This crossing on the main ditch is well defined and flowing.
CSAH # 22	This crossing of a branch is defined but has no apparent flow. Pond excavated on the south side of the road.

ACTIVITIES:

The concrete blocks that had been placed on the ditch as a dam have been removed as requested. (See letter from Dan Klint and the response.)

The County Board ,in response to a petition for a ditch repair, ordered an Engineer's report for this ditch in about 1988. See the ditch file for details.



CO DIT #27