

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *28* Branch No *4*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
<i>Between Stake No. 0</i>	<i>2.0</i>	<i>2 ft</i>	<i>4.0</i>		
<i>and Stake No. 1</i>	<i>1.9</i>		<i>3.9</i>	<i>22</i>	<i>✓</i>
<i>2</i>	<i>1.8</i>	<i>"</i>	<i>3.8</i>	<i>20</i>	<i>✓</i>
<i>3</i>	<i>1.7</i>	<i>"</i>	<i>3.7</i>	<i>19</i>	<i>✓</i>
<i>4</i>	<i>1.7</i>	<i>"</i>	<i>3.7</i>	<i>18</i>	<i>✓</i>
<i>5</i>	<i>1.6</i>	<i>"</i>	<i>3.6</i>	<i>17</i>	<i>✓</i>
<i>6</i>	<i>1.7</i>	<i>"</i>	<i>3.7</i>	<i>17</i>	<i>✓</i>
<i>7</i>	<i>1.6</i>	<i>"</i>	<i>3.6</i>	<i>17</i>	<i>✓</i>
<i>8</i>	<i>1.7</i>	<i>"</i>	<i>3.7</i>	<i>17</i>	<i>✓</i>
<i>9</i>	<i>1.8</i>	<i>"</i>	<i>3.8</i>	<i>19</i>	<i>✓</i>
<i>10</i>	<i>2.1</i>	<i>"</i>	<i>4.1</i>	<i>22</i>	<i>✓</i>
<i>11</i>	<i>1.6</i>	<i>"</i>	<i>3.6</i>	<i>20</i>	<i>✓</i>
<i>12</i>	<i>1.5</i>	<i>"</i>	<i>3.5</i>	<i>16</i>	<i>✓</i>
<i>13</i>	<i>1.5</i>	<i>"</i>	<i>3.5</i>	<i>15</i>	<i>✓</i>
<i>14</i>	<i>1.9</i>	<i>"</i>	<i>3.9</i>	<i>18</i>	<i>✓</i>
<i>15</i>	<i>1.6</i>	<i>"</i>	<i>3.6</i>	<i>19</i>	<i>✓</i>
<i>16</i>	<i>2.0</i>	<i>"</i>	<i>4.0</i>	<i>19</i>	<i>✓</i>
<i>17</i>	<i>2.0</i>	<i>"</i>	<i>4.0</i>	<i>22</i>	<i>✓</i>
<i>18</i>	<i>2.0</i>	<i>"</i>	<i>4.0</i>	<i>22</i>	<i>✓</i>
<i>19</i>	<i>1.5</i>	<i>"</i>	<i>3.5</i>	<i>19</i>	<i>✓</i>
				<i>358</i>	
				<i>10</i>	
					<i>Totals</i>

All - Dig (6) Cuts by M

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *28 Branch No 4*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>20</i>	<i>2.0</i>	<i>2 ft</i>	<i>4.0</i>	<i>19</i>	✓
and Stake No. <i>1</i>	<i>1.9</i>		<i>3.9</i>	<i>22</i>	
<i>2</i>	<i>2.1</i>	"	<i>2.1</i>	<i>19</i>	✓
<i>3</i>	<i>2.7</i>	"	<i>2.7</i>	<i>15</i>	✓
<i>4</i>	<i>2.5</i>		<i>2.5</i>	<i>29</i>	✓
<i>5</i>	<i>2.5</i>	"	<i>2.5</i>	<i>27</i>	✓
<i>6</i>	<i>2.6</i>		<i>2.6</i>	<i>28</i>	✓
<i>7</i>	<i>2.1</i>	"	<i>2.1</i>	<i>28</i>	✓
<i>+ 52</i>	<i>2.4</i>		<i>2.4</i>	<i>14</i>	✓
				<i>201</i>	
					<i>All six cents per yard</i>
					<i>Estimated Branch 4</i>
					<i>559 yds EX @ 6¢ = \$39.04</i>
					<i>Totals</i>

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 28 Branch no 5

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>0</u>	<u>1.9</u>	<u>2 ft</u>	<u>3.9</u>		
and Stake No. <u>1</u>	<u>1.3</u>		<u>3.3</u>	<u>17</u>	
<u>2</u>	<u>2.1</u>	"	<u>4.1</u>	<u>18</u>	
<u>3</u>	<u>1.5</u>	"	<u>3.5</u>	<u>19</u>	
<u>4</u>	<u>2.0</u>	"	<u>4.0</u>	<u>19</u>	
<u>5</u>	<u>1.3</u>	"	<u>3.3</u>	<u>17</u>	
<u>6</u>	<u>1.8</u>	"	<u>3.8</u>	<u>16</u>	
<u>7</u>	<u>2.6</u>	"	<u>4.6</u>	<u>25</u>	
<u>8</u>	<u>4.0</u>	"	<u>6.0</u>	<u>45</u>	
<u>9</u>	<u>3.6</u>	"	<u>5.6</u>	<u>70</u>	
<u>10</u>	<u>3.6</u>	"	<u>5.6</u>	<u>51</u>	
<u>11</u>	<u>3.4</u>	"	<u>5.4</u>	<u>49</u>	
<u>12</u>	<u>3.5</u>	"	<u>5.5</u>	<u>48</u>	
<u>13</u>	<u>3.4</u>	"	<u>5.4</u>	<u>48</u>	
<u>14</u>	<u>3.2</u>	"	<u>5.2</u>	<u>45</u>	
<u>15</u>	<u>3.4</u>	"	<u>5.4</u>	<u>45</u>	
<u>16</u>	<u>3.5</u>	"	<u>5.5</u>	<u>48</u>	
<u>17</u>	<u>3.6</u>	"	<u>5.6</u>	<u>50</u>	
<u>18</u>	<u>3.3</u>	"	<u>5.3</u>	<u>48</u>	
<u>19</u>	<u>2.9</u>	"	<u>4.9</u>	<u>41</u>	
<u>20</u>	<u>3.0</u>	"	<u>5.0</u>	<u>38</u>	
<u>21</u>	<u>3.0</u>	"	<u>5.0</u>	<u>7</u>	
Totals				<u>764</u>	

All-dirt (6) cents per yard

*Estimated Branch 5
764 yds @ 6¢ = \$45.84*

764

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 28 Branch No 6

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 0	1.0	2 ft	3.0	10	✓
and Stake No. 1	1.0		3.0		
2	2.0	"	4.0	15	✓
3	1.1	"	3.1	16	✓
4	1.8	"	3.8	15	✓
5	2.7	"	4.7	26	✓
6	3.0	"	5.0	36	✓
7	3.5	"	5.5	44	✓
8	3.6	"	5.6	46	✓
9	3.3	"	5.3	46	✓
10	2.6	"	4.6	36	✓
11	2.5	"	4.5	48	✓
12	2.3	"	4.3	8	✓
13	2.7	"	4.7	0	✓
14	2.6	"	4.6	0	✓
15	2.6	"	4.6	0	✓
				444	
				7	

All in (6) Cent. per yd

Estimated Branch No 6

444 yds Exc @ 6 = 26.64
 Bridge of plank with 11/8 = 7.00
 Total = \$ 33.64

Totals

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *28 Branch No 7*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>0</i>	<i>1.7</i>	<i>2 ft</i>	<i>3.7</i>		
and Stake No. <i>1</i>	<i>1.7</i>		<i>3.7</i>	<i>19</i>	✓
<i>2</i>	<i>1.8</i>	"	<i>3.8</i>	<i>19</i>	✓
<i>3</i>	<i>1.9</i>	"	<i>3.9</i>	<i>20</i>	✓
<i>4</i>	<i>1.9</i>	"	<i>3.9</i>	<i>21</i>	✓
<i>5</i>	<i>2.1</i>	"	<i>4.1</i>	<i>22</i>	✓
<i>6</i>	<i>2.1</i>	"	<i>4.1</i>	<i>24</i>	✓
<i>7</i>	<i>2.2</i>	"	<i>4.2</i>	<i>25</i>	✓
<i>8</i>	<i>2.2</i>	"	<i>4.2</i>	<i>25</i>	✓
<i>9</i>	<i>2.2</i>	"	<i>4.2</i>	<i>25</i>	✓
<i>10</i>	<i>2.2</i>	"	<i>4.2</i>	<i>26</i>	✓
<i>11</i>	<i>2.3</i>	"	<i>4.3</i>	<i>27</i>	✓
<i>12</i>	<i>2.3</i>	"	<i>4.3</i>	<i>27</i>	✓
<i>13</i>	<i>2.5</i>	"	<i>4.5</i>	<i>28</i>	✓
<i>14</i>	<i>2.5</i>	"	<i>4.5</i>	<i>30</i>	✓
<i>15</i>	<i>2.6</i>	"	<i>4.6</i>	<i>31</i>	✓
<i>16</i>	<i>2.5</i>	"	<i>4.5</i>	<i>31</i>	✓
<i>17</i>	<i>2.6</i>	"	<i>4.6</i>	<i>31</i>	✓
<i>18</i>	<i>2.7</i>	"	<i>4.7</i>	<i>33</i>	✓
<i>19</i>	<i>2.9</i>	"	<i>4.9</i>	<i>34</i>	✓
				<i>408</i>	
<i>Totals</i>					

Att- Price 6 Cents per yard

