

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No.....

SECTION	TIME WITHIN WHICH WORK MUST BE DONE	MANNER IN WHICH WORK MUST BE DONE	MATERIALS USED	COST OF MATERIALS AND WORK
Stake No. 0 to Stake No. 50	September 1 st 1889	If ditching machine is used to make front of ditch that portion thrown out by hand must be deposited outside that left by machine - otherwise all must be thrown two feet or over from edge of bank		All Excavation - Estimated at 8¢ per yard
50 to 104	August 15 th 1889	Same as above		
104 to 154	August 1 st 1889	Same as above		
154 to 204	July 15 th 1889	Same as above		
204 to 230	July 1 st 1889	Same as above		

Ditch No. 3

EXHIBIT 2.

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

*Sparks Ditch
No*

*Time and manner of
doing work*

No. 680.—Pioneer Press Co., St. Paul, Minn.

*Filed January 26th 1889.
G. M. Putnam
County Auditor*