

EXHIBIT I.

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

Ditch No 32

Branch No 2

Estimate of cost
= \$12,252

No. 686.— Pioneer Press Co., St. Paul, Minn.

Filed July 11th 1898
J. M. Putnam
Co Auditor

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 2

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>0</u>	<u>1.3</u>	<u>diff</u>	<u>3.9</u>		
and Stake No. <u>1</u>	<u>2.6</u>		<u>5.9</u>	<u>25</u>	✓
<u>2</u>	<u>2.2</u>	"	<u>5.3</u>	<u>34</u>	✓
<u>3</u>	<u>3.6</u>		<u>7.4</u>	<u>34</u>	✓
<u>4</u>	<u>2.1</u>	"	<u>5.7</u>	<u>41</u>	✓
<u>5</u>	<u>2.2</u>		<u>5.3</u>	<u>29</u>	✓
<u>6</u>	<u>2.0</u>	"	<u>5.0</u>	<u>28</u>	✓
<u>7</u>	<u>1.9</u>		<u>4.8</u>	<u>25</u>	✓
<u>8</u>	<u>1.8</u>	"	<u>4.7</u>	<u>24</u>	✓
<u>9</u>	<u>1.9</u>		<u>4.8</u>	<u>24</u>	✓
<u>10</u>	<u>1.9</u>	"	<u>4.8</u>	<u>25</u>	✓
<u>11</u>	<u>1.3</u>		<u>3.9</u>	<u>19</u>	✓
<u>12</u>	<u>2.2</u>	"	<u>5.3</u>	<u>23</u>	✓
<u>13</u>	<u>4.1</u>		<u>8.1</u>	<u>51</u>	✓
<u>14</u>	<u>2.3</u>	"	<u>5.4</u>	<u>52</u>	✓
<u>15</u>	<u>2.5</u>		<u>5.7</u>	<u>34</u>	✓
<u>16</u>	<u>2.8</u>	"	<u>6.2</u>	<u>39</u>	✓
<u>17</u>	<u>2.9</u>		<u>6.3</u>	<u>44</u>	✓
<u>18</u>	<u>3.1</u>	"	<u>6.6</u>	<u>47</u>	✓
<u>19</u>	<u>3.2</u>		<u>6.8</u>	<u>51</u>	✓
				<u>649</u>	
				<u>8</u>	
					Totals

All dirt cut for yard

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *32 Branch 202*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>20</i>	<i>3.3</i>	<i>Diff.</i>	<i>6.9</i>	<i>53</i>	<i>Ditch Center for ga</i>
and Stake No. <i>1</i>	<i>3.1</i>		<i>6.6</i>	<i>52</i>	
<i>2</i>	<i>2.9</i>	<i>"</i>	<i>6.3</i>	<i>47</i>	
<i>3</i>	<i>2.9</i>	<i>"</i>	<i>6.3</i>	<i>45</i>	
<i>4</i>	<i>2.9</i>	<i>"</i>	<i>6.3</i>	<i>45</i>	
<i>5</i>	<i>2.8</i>	<i>"</i>	<i>6.2</i>	<i>44</i>	
<i>6</i>	<i>3.1</i>	<i>"</i>	<i>6.6</i>	<i>46</i>	
<i>7</i>	<i>2.6</i>	<i>"</i>	<i>5.9</i>	<i>44</i>	
<i>8</i>	<i>2.5</i>	<i>"</i>	<i>5.7</i>	<i>37</i>	
<i>9</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>38</i>	
<i>10</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>40</i>	
<i>11</i>	<i>3.0</i>	<i>"</i>	<i>6.5</i>	<i>44</i>	
<i>12</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>28 44</i>	
<i>13</i>	<i>2.5</i>	<i>"</i>	<i>5.7</i>	<i>21 38</i>	
<i>14</i>	<i>2.6</i>	<i>"</i>	<i>5.9</i>	<i>21 37</i>	
<i>15</i>	<i>2.6</i>	<i>"</i>	<i>5.9</i>	<i>21 38</i>	
<i>16</i>	<i>2.4</i>	<i>"</i>	<i>5.6</i>	<i>20 36</i>	
<i>17</i>	<i>2.5</i>	<i>"</i>	<i>5.7</i>	<i>20 35</i>	
<i>18</i>	<i>2.4</i>	<i>"</i>	<i>5.6</i>	<i>18 35</i>	
<i>19</i>	<i>2.5</i>	<i>"</i>	<i>5.7</i>	<i>19 35</i>	
				<i>723</i>	
				<i>703</i>	
					Totals

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch No 2

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>40</u>	<u>2.2</u>	<u>2 ft</u>	<u>5.3</u>	<u>20</u>	✓
and Stake No. <u>1</u>	<u>2.6</u>		<u>5.9</u>	<u>20</u>	✓
<u>2</u>	<u>2.5</u>		<u>5.7</u>	<u>20</u>	✓
<u>3</u>	<u>2.4</u>		<u>5.6</u>	<u>18</u>	✓
<u>4</u>	<u>2.5</u>		<u>5.7</u>	<u>18</u>	✓
<u>+ 60</u>	<u>3.8</u>		<u>7.7</u>	<u>20</u>	✓
<u>5</u>	<u>2.5</u>		<u>5.7</u>	<u>42</u>	✓
<u>6</u>	<u>2.5</u>		<u>5.7</u>	<u>20</u>	✓
<u>7</u>	<u>3.0</u>		<u>6.5</u>	<u>23</u>	✓
<u>8</u>	<u>2.4</u>		<u>5.6</u>	<u>19</u>	✓
<u>9</u>	<u>3.0</u>	<u>6.5</u>	<u>18</u>	✓	
<u>50</u>	<u>2.4</u>	<u>5.5</u>	<u>20</u>	✓	
<u>1</u>	<u>2.5</u>	<u>5.7</u>	<u>17</u>	✓	
<u>2</u>	<u>2.6</u>	<u>5.9</u>	<u>16</u>	✓	
<u>3</u>	<u>2.6</u>	<u>5.9</u>	<u>15</u>	✓	
<u>4</u>	<u>3.8</u>	<u>7.7</u>	<u>16</u>	✓	
<u>+ 50</u>	<u>4.0</u>	<u>8.0</u>	<u>11</u>	✓	
<u>5</u>	<u>3.0</u>	<u>6.5</u>	<u>22</u>	✓	
<u>6</u>	<u>2.8</u>	<u>6.2</u>	<u>15</u>	✓	
<u>7</u>	<u>2.7</u>	<u>6.0</u>	<u>13</u>	✓	
			<u>352</u>		
					<i>Totals</i>

All dirt (6) cut to surface

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *32 Branch 202*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>58</i>	<i>3.0</i>	<i>2 ft</i>	<i>6.5</i>	<i>13</i>	<i>All dirt (6) Cent of per yd</i>
and Stake No. <i>59</i>	<i>3.0</i>		<i>6.5</i>	<i>10</i>	
<i>60</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>13</i>	
<i>1</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>12</i>	
<i>54</i>	<i>2.7</i>	<i>"</i>	<i>6.0</i>	<i>11</i>	
<i>55</i>	<i>3.0</i>	<i>"</i>	<i>6.5</i>	<i>10</i>	
<i>56</i>	<i>3.2</i>	<i>"</i>	<i>6.8</i>	<i>13</i>	
<i>57</i>	<i>2.6</i>	<i>"</i>	<i>5.9</i>	<i>13</i>	
<i>58</i>	<i>2.5</i>	<i>"</i>	<i>5.7</i>	<i>10</i>	
<i>59</i>	<i>2.4</i>	<i>"</i>	<i>5.6</i>	<i>10</i>	
<i>60</i>	<i>1.7</i>	<i>"</i>	<i>4.5</i>	<i>9</i>	
<i>61</i>	<i>1.2</i>	<i>"</i>	<i>3.5</i>	<i>9</i>	
<i>62</i>	<i>1.7</i>	<i>"</i>	<i>3.8</i>	<i>9</i>	
<i>63</i>	<i>2.4</i>	<i>"</i>	<i>4.5</i>	<i>9</i>	
<i>64</i>	<i>3.0</i>	<i>"</i>	<i>5.6</i>	<i>9</i>	
<i>65</i>	<i>3.0</i>	<i>3 ft</i>	<i>6.5</i>	<i>10</i>	
<i>66</i>	<i>3.0</i>		<i>7.5</i>	<i>15</i>	
<i>67</i>	<i>3.0</i>	<i>"</i>	<i>7.5</i>	<i>17</i>	
<i>68</i>	<i>2.8</i>	<i>"</i>	<i>7.2</i>	<i>16</i>	
<i>69</i>	<i>2.8</i>	<i>"</i>	<i>7.2</i>	<i>16</i>	
				<i>214</i>	
					<i>Totals</i>

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *32 Branch No 2*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>78</i>	<i>2.8</i>	<i>3 ft</i>	<i>7.2</i>	<i>16</i>	✓
and Stake No. <i>79</i>	<i>3.0</i>	<i>"</i>	<i>7.5</i>	<i>17</i>	✓
<i>750</i>	<i>3.5</i>	<i>"</i>	<i>8.2</i>	<i>00</i>	✓
<i>80</i>	<i>3.2</i>	<i>"</i>	<i>7.8</i>	<i>33</i>	✓
<i>1</i>	<i>2.5</i>	<i>"</i>	<i>6.7</i>	<i>23</i>	✓
<i>2</i>	<i>2.2</i>	<i>"</i>	<i>6.3</i>	<i>11</i>	✓
<i>+30</i>	<i>2.2</i>	<i>"</i>	<i>6.3</i>	<i>4</i>	<i>17 1/2</i>
				<i>104</i>	
					<i>Totals</i>

All dip (6) Curve by eye
Estimated Branch No 2
2042 yds Ex @ 6¢ = 122.52