

No 37

EXHIBIT 2.

VIEWERS' REPORT

— IN —

DITCH PROCEEDINGS.

Filed Oct. 4th 1899
Selden H. Gaffney
Co. Auditor

No. 680.— Pioneer Press Co., St. Paul, Minn.

NAME
ADDRESS
CITY
STATE

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page]

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No. 37.

SECTION
TIME WITHIN WHICH
WORK MUST BE
DONE

MANNER IN WHICH WORK
MUST BE DONE

MATERIALS
USED

COST OF
MATERIALS
AND WORK

Stake No. 19
TO

Stake No. 25448

The form of ditch will be as flat bottom with sides sloping one to one. All material must be taken from the ditch and thrown 2 feet from edge of bank of ditch when completed. When ditch runs through timber or brush all such brush must be cleared and deposited at least 4 feet from edge of completed ditch.

Stake No.
TO

Stake No.

Stake No. 123420
TO

Stake No.

Stake No.
TO

Stake No.

a Bridge for road of 2 mud dills 12"x6" 16' long 8 stringers 6"x6" 10 1/2' long mud dill to be 1 1/2' from ditch bank and stringers to be spaced to mud dill 12' spans 12"x3"x16'

\$ 18 00

Stake No. 221+3
TO

Stake No.

Bridge same as above

\$ 18 00

Stake No.
TO

Stake No.

Stake No.
TO

Stake No.

Stake No.
TO

Stake No.