

# VIEWERS' REPORT

—IN—

## DITCH PROCEEDINGS.

*Ditch 38*

*Filed June 16<sup>th</sup> 1900  
Adm. No. 1467  
Co. Anderson*

No. 680.—Pioneer Press Co., St. Paul, Minn.

TO THE  
MANAGER  
OF THE

MINNESOTA  
WATERWAY

REPORT

NO. 1467

AD. NO.

FILED

JUN 16 1900

—IN—

VIEWERS' REPORT

*23*

*Ditch No. 38*

*23*

*[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page. The text appears to be a detailed report or list of items related to the ditch proceedings.]*

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No. 38

SECTION	TIME WITHIN WHICH WORK MUST BE DONE	MANNER IN WHICH WORK MUST BE DONE	MATERIALS USED	COST OF MATERIALS AND WORK
Stake No. 0 TO Stake No. 128+43	} June 1st 1901	<p>Call center taken from the ditch shall be thrown at least two feet from edge of the ditch except from Plat 84 to 91 when same shall be left any nearer than 8 ft from edge of ditch -</p> <p>From Plat 123 to 128+43 the earth shall be thrown on south side of ditch -</p> <p>Cutout at Plat 52+50 will consist of 16 - 3" x 12" x 16' plank laid on spiked to 4 stringers of not less than 16" diameter at small end - three stringers to be laid on middle side of opening as the stringers all the of small line back or forward - when completed stringers from north end be one 1 1/2 ft above water as surface -</p> <p>Bank must be cleaned away so as not be covered with dirt -</p> <p>Stakes are set five eighth from edge of ditch same with line of stakes - old stakes removed the first when they are within 8 ft of new one</p>		
Stake No. 0 TO Stake No. 128+43				
Stake No. 0 TO Stake No. 128+43				
Stake No. 0 TO Stake No. 128+43				
Stake No. 0 TO Stake No. 128+43				