

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. ....

(7)

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD	
Between Stake No. .... 107	2.4	2.0	6.8	44	\$ .08	✓
and Stake No. .... 108	2.3	"	6.6	42	\$ .08	✓
109	2.3	"	6.6	36	\$ .08	✓
110	2.5	"	7.0	39	\$ .08	✓
111	3.1	"	8.2	49	\$ .08	✓
112	2.8	"	7.6	55	\$ .08	✓
113	3.0	"	8.0	52	\$ .08	✓
114	3.1	"	8.2	55	\$ .08	✓
115	3.4	"	8.8	65	\$ .08	✓
116	3.4	"	8.8	68	\$ .08	✓
117	2.9	"	7.8	61	\$ .08	✓
118	2.9	"	7.8	52	\$ .08	✓
119	3.0	"	8.0	55	\$ .08	✓
120	2.3	"	6.6	44	\$ .08	✓
121	2.5	"	7.0	39	\$ .08	✓
122	2.7	"	7.4	44	\$ .08	✓
123	2.7	"	7.4	47	\$ .08	✓
124	2.8	"	7.6	47	\$ .08	✓
125	2.4	"	6.8	44	\$ .08	✓
126	2.7	"	7.4	44	\$ .08	✓
				98 <sup>2</sup> / <sub>10</sub>		
<i>Totals</i>						

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and  
 (8) Cost of same, in Ditch No.....

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD	
Between Stake No.....127	2.5	2.0	7.0	44	\$ .08	✓
and Stake No.....128	3.0	"	8.0	47	\$ .08	✓
129	3.0	"	8.0	55	\$ .08	✓
130	3.1	"	8.2	55	\$ .08	✓
131	3.2	"	8.4	58	\$ .08	✓
132	3.0	"	8.0	58	\$ .08	✓
133	3.0	"	8.0	55	\$ .08	✓
134	3.0	"	8.0	55	\$ .08	✓
135	2.7	"	7.4	52	\$ .08	✓
136	2.9	"	7.8	49	\$ .08	✓
137	2.5	"	7.0	47	\$ .08	✓
138	2.5	"	7.0	42	\$ .08	✓
139	2.5	"	7.0	42	\$ .08	✓
140	3.0	"	8.0	47	\$ .08	✓
141	2.6	2.0	7.2	49	\$ .08	✓
142	2.9	"	7.8	47	\$ .08	✓
143	3.0	"	8.0	52	\$ .08	✓
144	2.9	"	7.8	52	\$ .08	✓
145	2.8	2.0	7.6	52	\$ .08	✓
146	2.9	"	7.8	52	\$ .08	✓
				1010		
				10		
<i>Totals</i>						

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. (9).....

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD	
Between Stake No. 147	2.9	2.0	7.8	52	\$ .08	✓
and Stake No. 148	2.7	"	7.4	49	\$ .08	✓
149	2.5	"	7.0	44	\$ .08	✓
150	2.8	"	7.6	44	\$ .08	✓
151	2.7	"	7.4	47	\$ .08	✓
152	2.4	"	6.8	42	\$ .08	✓
153	2.6	"	7.2	42	\$ .08	✓
154	2.9	"	7.8	49	\$ .08	✓
155	2.9	"	7.8	52	\$ .08	✓
156	2.9	"	7.4	49	\$ .08	✓
157	2.7	"	7.4	47	\$ .08	✓
158	2.8	"	7.6	47	\$ .08	✓
159	2.6	"	7.2	47	\$ .08	✓
160	2.7	"	7.4	47	\$ .08	✓
161	2.4	"	6.8	42	\$ .08	✓
162	2.6	"	7.2	42	\$ .08	✓
163	2.6	"	7.2	44	\$ .08	✓
164	3.1	"	8.2	52	\$ .08	✓
165	3.2	"	8.4	58	\$ .08	✓
166	3.2	"	8.4	61	\$ .08	✓
				957		
<i>Totals</i>						

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. ....

(10)

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 167	3.4	2.0	8.8	65	\$ .08 ✓
and Stake No. 168	3.4	"	8.8	68	\$ .08 ✓
169	3.1	"	8.2	61	\$ .08 ✓
170	3.5	"	9.0	65	\$ .08 ✓
171	3.5	"	9.0	71	\$ .08 ✓
172	3.2	"	8.4	65	\$ .08 ✓
173	2.9	"	7.8	55	\$ .08 ✓
174	2.6	"	7.2	49	\$ .08 ✓
175	2.6	"	7.2	44	\$ .08 ✓
176	2.5	"	7.0	42	\$ .08 ✓
177	2.2	"	6.4	39	\$ .08 ✓
178	2.7	"	7.4	42	\$ .08 ✓
179	2.7	"	7.4	47	\$ .08 ✓
180	3.1	"	8.2	52	\$ .08 ✓
181	3.0	"	8.0	55	\$ .08 ✓
182	2.4	"	6.8	54	\$ .08 ✓
183	3.2	"	8.4	45	\$ .08 ✓
184	3.1	"	8.2	58	\$ .08 ✓
185	2.9	"	7.8	55	\$ .08 ✓
186	2.7	"	7.4	49	\$ .08 ✓
				1081	
				10	
<i>Totals</i>					

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No.....

SECTION (11)	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 187	2.6	2.0	7.2	47	\$ .08 ✓
and Stake No. 188	2.3	"	6.6	39	\$ .08 ✓
189	2.2	"	6.4	34	\$ .08 ✓
190	2.6	"	7.2	39	\$ .08 ✓
191	2.4	"	6.8	42	\$ .08 ✓
192	2.0	"	6.0	34	\$ .08 ✓
193	2.0	"	6.0	30	\$ .08 ✓
194	2.2	"	6.4	32	\$ .08 ✓
195	1.9	"	5.8	30	\$ .08 ✓
196	1.9	"	5.8	28	\$ .08 ✓
197	1.6	"	5.2	23	\$ .08 ✓
198	1.9	"	5.8	23	\$ .08 ✓
199	1.7	"	5.4	25	\$ .08 ✓
200	2.3	"	6.6	30	\$ .08 ✓
201	2.2	"	6.4	34	\$ .08 ✓
202	2.0	"	6.0	32	\$ .08 ✓
203	2.1	"	6.2	32	\$ .08 ✓
204	2.2	"	6.4	34	\$ .08 ✓
205	2.3	"	6.6	30	\$ .08 ✓
206	2.4	"	6.8	39	\$ .08 ✓
				657	
<i>Totals</i>					

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No.....

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD	Lookings	cu yds.
(12) Between Stake No..... 207	2.4	2.0	6.8	39	\$ .08		
and Stake No..... 208	2.7	2.0	7.4	44	\$ .08	Sheet No 1	675
209	2.8	2.0	7.6	47	\$ .08		
210	2.5	2.0	7.0	47	\$ .08	" "	2 903
211	2.4	2.0	6.8	5	\$ .08	" "	3 724
				182		" "	4 605
				3		" "	5 1008
						" "	6 1083
						" "	7 982
						" "	8 1010
						" "	9 957
						" "	10 1081
						" "	11 657
						" "	12 182
							9867
						Total	9867 cubic yds
							9827 cu yds at 8 cents
							per cu yd = \$ 789.36
					9867 08 789.36	Totals	