

County Ditch Number 65

| Culvert Number | Culvert Location (Cross street or Address) | Date Visited | Culvert Material | Culvert Size (inches) | Culvert Length (feet) | Culvert Condition | Culvert Flowing | Amount of Silt (feet) Up / Down | Upstream Invert Elev. (NGVD 29) | Downstream Invert Elev. (NGVD 29) | Upstream Culvert Coordinates Northing / Easting (Anoka County coordinates) | Downstream Culvert Coordinates Northing / Easting (Anoka County coordinates) | Benchmark Location (on Road crossings only) | Benchmark Elevation (NGVD 29) | Picture File Names | Notes |
|--------------------------|-------------------------------------------------------|---------------------|-------------------------|----------------------------------|----------------------------------|---------------------------|------------------------|--------------------------------------------|--------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|------------------------------------------|----------------------------------------------------|----------------------------------------------------------------------------------------------------------|
| 1 | 18281 Uranium St. NW, Nowthen, MN | 03/15/2012 | CMP | 36 | 8 | good | yes | none | 878.3 | 878.2 | 197456.4 / 459321.1 | 197451.2 / 459327.0 | | | 1-Up / 1-Down | |
| 2 | 18281 Uranium St. NW, Nowthen, MN | 03/15/2012 | RCP | 36 | 19 | good | yes | none | 878.4 | 878.4 | 197538.2 / 459269.5 | 197519.1 / 459272.0 | | | 2-Up / 2-Down | |
| 3 | 6330 185th Ave. NW, Nowthen, MN | 03/15/2012 | RCP | 36 | 16 | poor | yes | 0.3 / 0.3 | 879.5 | 880.0 | 197701.5 / 459255.8 | 197685.8 / 459255.5 | | | 3-Up / 3-Down / 3-Middle | Culvert is collapsed in the center. |
| Bridge-1 | 6330 185th Ave. NW, Nowthen, MN | 03/15/2012 | | | | | | | | | | | | | Bridge-1 | Wooden Bridge Coordinates, Approximate Center: 197874 / 459333 |
| Bridge-2 | 6330 185th Ave. NW, Nowthen, MN | 03/15/2012 | | | | | | | | | | | | | Bridge-2 | Wooden Bridge Coordinates, Approximate Center: 198016 / 459201 |
| 4A | 6330 185th Ave. NW, Nowthen, MN | 03/15/2012 | RCP- Up/CMP- Down | 15-Up/18- Down | 46 | good | yes | none | 890.0 | 889.9 | 198249.2 / 458869.5 | 198261.0 / 458913.4 | | | 4A & 4B-Up / 4A & 4B- Down | Note the different type of culvert at each end. |
| 4B | 6330 185th Ave. NW, Nowthen, MN | 03/15/2012 | RCP- Up/CMP- Down | 15-Up/18- Down | 45 | good | yes | none | 889.8 | 889.8 | 198246.4 / 458870.7 | 198258.7 / 458914.0 | | | 4A & 4B-Up / 4A & 4B- Down / 4B-Up Break In RCP | Note the different type of culvert at each end. There is a break in the RCP as shown on the photo. |
| Bridge-3 | 6350 185th Ave. NW, Nowthen, MN | 03/15/2012 | | | | | | | | | | | | | Bridge-3 | Concrete Bridge Coordinates, Approximate Center: 198216 / 458735 |
| 5 | 6350 185th Ave. NW, Nowthen, MN | 03/15/2012 | RCP- Up/CMP- Down | 21-Up/30- Down | 37 | poor- Up/good- Down | yes | none | 894.7 | 894.4 | 198559.0 / 458566.2 | 198525.5 / 458581.5 | | | 5-Up / 5-Down | Note the different type of culvert at each end. The RCP (5-UP) is split at the top of the pipe. |
| 6 | 185th Ave. NW, Nowthen, MN | 03/15/2012 | CMP | 24 | 80 | good | yes | none | 897.0 | 896.6 | 198893.5 / 458206.9 | 198825.2 / 458248.8 | RR Spike in Power Pole #69340 - South Side of 185th Ave. NW - Approx. 500 Ft. West of Culvert No.6 | 906.10 | 6-Up / 6-Down | |
| 7 | 6475 185th Ave. NW, Nowthen, MN | 03/16/2012 | CMP | 30 | 28 | good | yes | minimal | 898.0 | 897.9 | 199898.8 / 457744.0 | 199884.0 / 457767.4 | | | 7-Up / 7-Down | |
| 8 | 18996 Yttrium St. NW, Nowthen, MN | 03/16/2012 | CMP | 24 | 20 | good | yes | none | 902.8 | 902.6 | 202149.3 / 457322.2 | 202131.9 / 457312.9 | | | 8-Up / 8-Down | There are CMP flared end sections on each end of the culvert. |
| 9 | 191st Ave. NW, Nowthen, MN | 03/16/2012 | CMP | 18 | 54 | good | yes | minimal | 905.1 | 904.3 | 202841.8 / 457205.4 | 202797.5 / 457174.6 | RR Spike in N. Face of Power Pole #59327 - South Side of 191st Ave. NW - Approx. 30 Ft. East of Culvert No.9 | 912.36 | 9-Up / 9-Down | |
| 10 - Lateral No. 3 | 18933 Yttrium St. NW, Nowthen, MN | 03/16/2012 | CMP | 15 | 22 | good- Up/poor- Down | yes | none | 903.8 | 903.9 | 201925.6 / 457765.7 | 201915.3 / 457746.2 | | | 10-Up / 10-Down | Part of the bottom of the upstream end of the culvert is rotted away. |