

*Ditch No. 12*

EXHIBIT I.

**VIEWERS' REPORT**

**DITCH PROCEEDINGS.**

No. 686.—Pioneer Press Co., St. Paul, Minn.

*Filed October 17<sup>th</sup> 1890*  
*J. M. Putnam*  
*County Auditor*

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 12 - Main Line -

SECTION	DEPTH OF CUT Feet	WIDTH OF CUT AT BOTTOM Feet	WIDTH OF CUT AT TOP Feet	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 95				6663	
and Stake No. 96 ✓	3.8	3.0	10.6	96	\$ .08
97 ✓	3.8	3.0	10.6	96	\$ .08
98 ✓	3.8	3.0	10.6	96	\$ .08
99 ✓	3.7	3.0	10.4	94	\$ .08
100 ✓	3.9	3.0	10.8	96	\$ .08
101 ✓	3.7	3.0	10.4	96	\$ .08
102 ✓	3.6	3.0	10.2	90	\$ .08
103 ✓	3.8	3.0	10.6	92	\$ .08
104 ✓	3.8	3.0	10.6	96	\$ .08
105 ✓	3.8	3.0	10.6	96	\$ .08
106 ✓	3.9	3.0	10.8	98	\$ .08
107 ✓	3.8	3.0	10.6	98	\$ .08
108 ✓	3.8	3.0	10.6	96	\$ .08
109 ✓	3.8	3.0	10.6	96	\$ .08
110 ✓	3.8	3.0	10.6	96	\$ .08
111 ✓	3.8	3.0	10.6	96	\$ .08
112 ✓	3.7	3.0	10.4	94	\$ .08
113 ✓	3.8	3.0	10.6	94	\$ .08
114 ✓	3.8	3.0	10.6	96	\$ .08
				8475	
<b>Totals</b>					



EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 12 - Main Line -

SECTION	DEPTH OF CUT <i>Feet</i>	WIDTH OF CUT AT BOTTOM <i>Feet</i>	WIDTH OF CUT AT TOP <i>Feet</i>	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 133				10082	
and Stake No. 134 ✓	2.2	3.0	7.4	51	\$ .08
135 ✓	2.4	3.0	7.8	45	\$ .08
136 ✓	2.9	3.0	8.8	56	\$ .08
137 ✓	2.6	3.0	8.2	59	\$ .08
138 ✓	2.6	3.0	8.2	54	\$ .08
139 ✓	2.7	3.0	8.4	56	\$ .08
140 ✓	3.0	3.0	9.0	62	\$ .08
141 ✓	4.5	3.0	12.0	94	\$ .08
142 ✓	3.3	3.0	9.6	100	\$ .08
143 ✓	3.4	3.0	9.8	78	\$ .08
144 ✓	3.2	3.0	9.4	76	\$ .08
145 ✓	2.9	3.0	8.8	68	\$ .08
146 ✓	2.6	3.0	8.2	59	\$ .08
147 ✓	3.2	3.0	9.4	63	\$ .08
148 ✓	3.1	3.0	9.2	68	\$ .08
149 ✓	2.4	3.0	7.8	59	\$ .08
150 ✓	2.2	3.0	7.4	45	\$ .08
151 ✓	2.4	3.0	7.8	45	\$ .08
152 ✓	2.5	3.0	8.0	50	\$ .08
				11270	
<i>Totals</i>					

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 12 - Main Line —

(9)

SECTION	DEPTH OF CUT <i>Feet.</i>	WIDTH OF CUT AT BOTTOM <i>Feet</i>	WIDTH OF CUT AT TOP <i>Feet</i>	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 152				11270	
and Stake No. 153 ✓	2.7	3.0	8.4	54	\$ .08
154 ✓	3.8	3.0	8.6	59	\$ .08
155 ✓	2.9	3.0	8.8	62	\$ .08
156 ✓	2.9	3.0	8.8	63	\$ .08
157 ✓	2.5	3.0	8.0	57	\$ .08
158 ✓	2.4	3.0	7.8	49	\$ .08
159 ✓	4.0	3.0	11.0	94	\$ .08
160 ✓	2.9	3.0	8.8	82	\$ .08
161 ✓	3.2	3.0	9.4	68	\$ .08
162 ✓	3.1	3.0	9.2	71	\$ .08
163 ✓	3.1	3.0	9.2	69	\$ .08
164 ✓	3.0	3.0	9.0	68	\$ .08
165 ✓	2.9	3.0	8.8	65	\$ .08
166 ✓	3.0	3.0	9.0	64	\$ .08
167 ✓	2.9	3.0	8.8	65	\$ .08
168 ✓	3.0	3.0	9.0	64	\$ .08
169 ✓	2.9	3.0	8.8	65	\$ .08
170 ✓	2.8	3.0	8.6	62	\$ .08
171 ✓	2.8	3.0	8.6	60	\$ .08
				12511	
					Totals

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 12-Maid Linn—

(10)

SECTION	DEPTH OF CUT <i>Feet</i>	WIDTH OF CUT AT BOTTOM <i>Feet</i>	WIDTH OF CUT AT TOP <i>Feet</i>	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. 171				12511	
and Stake No. 172 ✓	2.8	3.0	8.6	6.0	\$ .08
173 ✓	2.6	3.0	8.2	57	\$ .08
174 ✓	2.7	3.0	8.4	56	\$ .08
175 ✓	2.4	3.0	7.8	53	\$ .08
176 ✓	2.5	3.0	8.0	50	\$ .08
177 ✓	2.1	3.0	7.2	45	\$ .08
178 ✓	2.7	3.0	8.4	48	\$ .08
179 ✓	2.4	3.0	7.8	53	\$ .08
180 ✓	2.0	3.0	7.0	42	\$ .08
181 ✓	1.8	3.0	6.6	34	\$ .08
182 ✓	2.0	3.0	7.0	34	\$ .08
183 ✓	1.9	3.0	6.8	33	\$ .08
184 ✓	2.2	3.0	7.4	38	\$ .08
185 ✓	1.0	3.0	5.0	27	\$ .08
186 ✓	0.7	4.0	5.4	24	\$ .08
187 ✓	1.3	4.0	6.6	15	\$ .08
188 ✓	2.9	4.0	9.8	47	\$ .08
189 ✓	2.8	4.0	9.6	73	\$ .08
190 ✓	3.3	4.0	10.6	80	\$ .08
				13382	
<i>Totals</i>					