

Ditch No. 13
EXHIBIT I.

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

No. 686.—Pioneer Press Co., St. Paul, Minn.

Filed March 30th 1891
J. W. Putnam
County Auditor

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13 - Main Line

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD |
|---------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|
| Between Stake No. 0 | 0.7 | 2.0 | 2.7 | | |
| and Stake No. 1 | 0.8 | 2.0 | 2.8 | 8 ✓ | \$.08 |
| 2 | 0.7 | 2.0 | 2.7 | 8 ✓ | \$.08 |
| 3 | 0.4 | 2.0 | 2.4 | 6 ✓ | \$.08 |
| 4 | 0.9 | 2.0 | 2.9 | 8 ✓ | \$.08 |
| 5 | 0.0 | 2.0 | 2.0 | 6 ✓ | \$.08 |
| 6 | 0.5 | 2.0 | 2.5 | 3 ✓ | \$.08 |
| 7 | 1.0 | 2.0 | 3.0 | 8 ✓ | \$.08 |
| 8 | 1.0 | 2.0 | 3.0 | 10 ✓ | \$.08 |
| 9 | 1.7 | 2.0 | 3.7 | 14 ✓ | \$.08 |
| 10 | 1.6 | 2.0 | 3.6 | 18 ✓ | \$.08 |
| 11 | 1.6 | 2.0 | 3.6 | 16 ✓ | \$.08 |
| 12 | 1.7 | 2.0 | 3.7 | 18 ✓ | \$.08 |
| 13 | 1.8 | 2.0 | 3.8 | 19 ✓ | \$.08 |
| 14 | 1.0 | 2.0 | 3.5 | 18 ✓ | \$.08 |
| 15 | 1.7 | 2.0 | 3.7 | 16 ✓ | \$.08 |
| 16 | 1.7 | 2.0 | 3.7 | 18 ✓ | \$.08 |
| 17 | 1.8 | 2.0 | 3.8 | 19 ✓ | \$.08 |
| 18 | 2.0 | 2.0 | 4.0 | 21 ✓ | \$.08 |
| 19 | 2.0 | 2.0 | 4.0 | 22 ✓ | \$.08 |
| | | | | 256 | |
| | | | | | <i>Totals</i> |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13 Main Line —

(2)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD |
|----------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|
| Between Stake No. 19 | | | | 256 | |
| and Stake No. 20 | 2.0 | 2.0 | 4.0 | 22 ✓ | \$.08 |
| 21 | 2.2 | 2.0 | 4.2 | 23 ✓ | \$.08 |
| 22 | 2.2 | 2.0 | 4.2 | 25 ✓ | \$.08 |
| 23 | 2.3 | 2.0 | 4.3 | 26 ✓ | \$.08 |
| 24 | 2.3 | 2.0 | 4.3 | 27 ✓ | \$.08 |
| 25 | 2.7 | 2.0 | 4.7 | 30 ✓ | \$.08 |
| 26 | 2.8 | 2.0 | 4.8 | 34 ✓ | \$.08 |
| 27 | 3.2 | 2.0 | 5.2 | 39 ✓ | \$.08 |
| 28 | 2.9 | 2.0 | 4.9 | 40 ✓ | \$.08 |
| 29 | 2.8 | 2.0 | 4.8 | 36 ✓ | \$.08 |
| 30 | 3.0 | 2.0 | 5.0 | 37 ✓ | \$.08 |
| 31 | 3.1 | 2.0 | 5.1 | 40 ✓ | \$.08 |
| 32 | 3.3 | 2.0 | 5.3 | 43 ✓ | \$.08 |
| 33 | 3.5 | 2.0 | 5.5 | 49 ✓ | \$.08 |
| 34 | 3.4 | 2.0 | 5.4 | 48 ✓ | \$.08 |
| 35 | 3.5 | 2.0 | 5.5 | 48 ✓ | \$.08 |
| 36 | 3.3 | 2.0 | 5.3 | 47 ✓ | \$.08 |
| 37 | 3.7 | 2.0 | 5.7 | 49 ✓ | \$.08 |
| 38 | 3.8 | 2.0 | 5.8 | 54 ✓ | \$.08 |
| | | | | 971 | |
| Totals | | | | | |

EXHIBIT I OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13 - Main Line -

(3)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD | |
|----------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|---------------|
| Between Stake No. 38 | | | | 971 | | |
| and Stake No. 39 | 3.5 | 2.0 | 5.5 | 52 ✓ | \$.08 | |
| 40 | 3.5 | 2.0 | 5.5 | 49 ✓ | \$.08 | |
| 41 | 3.5 | 2.0 | 5.5 | 49 ✓ | \$.08 | |
| 42 | 2.9 | 2.0 | 4.9 | 43 ✓ | \$.08 | |
| 43 | 3.0 | 2.0 | 5.0 | 38 ✓ | \$.08 | |
| 44 | 3.1 | 2.0 | 5.1 | 40 ✓ | \$.08 | |
| 45 | 2.6 | 2.0 | 4.6 | 36 ✓ | \$.08 | |
| 46 | 2.3 | 2.0 | 4.3 | 29 ✓ | \$.08 | |
| 47 | 2.5 | 2.0 | 4.5 | 28 ✓ | \$.08 | |
| 48 | 2.4 | 2.0 | 4.4 | 29 ✓ | \$.08 | |
| 49 | 2.3 | 2.0 | 4.3 | 28 ✓ | \$.08 | |
| 50 | 2.9 | 2.0 | 4.9 | 31 ✓ | \$.08 | |
| 51 | 2.2 | 2.0 | 4.2 | 31 ✓ | \$.08 | |
| 52 | 2.0 | 2.0 | 4.0 | 23 ✓ | \$.08 | |
| 53 | 0.0 | 0.0 | 0.0 | 10 ✓ | \$.08 | |
| 54 | 0.0 | 0.0 | 0.0 | | | In Grass Lake |
| 55 | 0.0 | 0.0 | 0.0 | | | do. |
| 56 | 0.0 | 0.0 | 0.0 | | | do. |
| 57 | 0.0 | 0.0 | 0.0 | | | do. |
| | | | | 1489 | | Totals |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13—Main Line —

(4)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD | |
|----------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|---------------|
| Between Stake No. 57 | 0.0 | | | 1487 | ✓ | |
| and Stake No. 58 | 0.0 | | | 0.0 | ✓ | In Grass Lake |
| 59 | 0.0 | | | | ✓ | do, |
| 60 | 0.0 | | | | ✓ | do, |
| 61 | 0.0 | | | | ✓ | do, |
| 62 | 0.0 | | | | ✓ | do, |
| 63 | 0.0 | | | | ✓ | do, |
| 64 | 0.0 | | | | ✓ | do, |
| 65 | 0.0 | | | | ✓ | do, |
| 66 | 0.0 | | | | ✓ | do, |
| 67 | 0.0 | | | | ✓ | do, |
| 68 | 0.0 | | | | ✓ | do, |
| 69 | 0.0 | | | | ✓ | do, |
| 70 | 0.0 | | | | ✓ | do, |
| 71 | 0.0 | | | | ✓ | do, |
| 72 | 0.0 | | | | ✓ | do, |
| 73 | 0.0 | | | | ✓ | do, |
| 74 | 0.0 | | | | ✓ | do, |
| 75 | 0.0 | | | | ✓ | do, |
| 76 | 0.0 | | | | ✓ | do, |
| | | | | 1487 | | Totals |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13 Main Line —

(5)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD | |
|-----------------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|--------|
| Between Stake No. <u>26</u> | 0,0 | | | 1487 | | |
| and Stake No. <u>27</u> | 0,0 | | | | | |
| <u>78</u> | 0,0 | | | | | |
| <u>79</u> | 0,0 | | | | | |
| <u>80</u> | 0,2 | 2,0 | 2,2 | 2 | \$.08 | |
| <u>81</u> | 1,0 | 2,0 | 3,0 | 6 | \$.08 | |
| <u>82</u> | 1,0 | 2,0 | 3,0 | 10 | \$.08 | |
| <u>83</u> | 1,1 | 2,0 | 3,1 | 11 | \$.08 | |
| <u>84</u> | 1,0 | 2,0 | 3,0 | 11 | \$.08 | |
| <u>85</u> | 1,1 | 2,0 | 3,1 | 11 | \$.08 | |
| <u>86</u> | 0,8 | 2,0 | 2,8 | 10 | \$.08 | |
| <u>87</u> | 0,6 | 2,0 | 2,6 | 7 | \$.08 | |
| <u>88</u> | 1,4 | 2,0 | 3,4 | 10 | \$.08 | |
| <u>89</u> | 1,7 | 2,0 | 3,7 | 16 | \$.08 | |
| <u>90</u> | 2,4 | 2,0 | 4,4 | 23 | \$.08 | |
| <u>91</u> | 3,8 | 2,0 | 5,8 | 41 | \$.08 | |
| <u>92</u> | 3,9 | 2,0 | 5,8 | 56 | \$.08 | |
| <u>93</u> | 4,9 | 2,0 | 11,8 | 90 | \$.08 | |
| <u>94</u> | 8,2 | 2,0 | 18,4 | 147 | \$.08 | |
| <u>95</u> | 4,6 | 2,0 | 11,2 | 140 | \$.08 | |
| | | | | 2078 | | |
| | | | | | | Totals |

In Grass Lake
do,
do,

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 18 Main Line -

(6)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD |
|-----------------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|
| Between Stake No. <u>95</u> | | | | 2078 | |
| and Stake No. <u>96</u> | 6.1 | 2.0 | 14.2 | 125 ✓ | \$.08 |
| 97 | 3.5 | 2.0 | 9.0 | 100 ✓ | \$.08 |
| 98 | 3.6 | 2.0 | 9.2 | 73 ✓ | \$.08 |
| 99 | 4.8 | 2.0 | 11.6 | 65 ✓ | \$.08 |
| 100 | 3.2 | 2.0 | 8.4 | 75 ✓ | \$.08 |
| 101 | 2.7 | 2.0 | 4.7 | 60 ✓ | \$.08 |
| 102 | 2.2 | 2.0 | 4.2 | 29 ✓ | \$.08 |
| 103 | 2.4 | 2.0 | 4.4 | 27 ✓ | \$.08 |
| 104 | 2.4 | 2.0 | 4.4 | 28 ✓ | \$.08 |
| 105 | 2.1 | 2.0 | 4.1 | 26 ✓ | \$.08 |
| 106 | 2.3 | 2.0 | 4.3 | 25 ✓ | \$.08 |
| 107 | 2.5 | 2.0 | 4.5 | 28 ✓ | \$.08 |
| 108 | 2.0 | 2.0 | 4.0 | 26 ✓ | \$.08 |
| 109 | 2.0 | 2.0 | 4.0 | 22 ✓ | \$.08 |
| 110 | 1.5 | 2.0 | 3.5 | 19 ✓ | \$.08 |
| 111 | 1.8 | 2.0 | 3.8 | 17 ✓ | \$.08 |
| 112 | 2.1 | 2.0 | 4.1 | 22 ✓ | \$.08 |
| 113 | 2.1 | 2.0 | 4.1 | 23 ✓ | \$.08 |
| 114 | 2.4 | 2.0 | 4.4 | 26 ✓ | \$.08 |
| | | | | 2894 | |
| | | | | | <i>Totals</i> |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 13—Main Line —

(4)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD |
|-----------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|
| Between Stake No. 114 | | | | 2894 | |
| and Stake No. 115 | | | | | |
| 116 | 1.7 | 2.0 | 3.7 | 23 | \$.08 |
| | 2.4 | 2.0 | 4.4 | 23 | \$.08 |
| 117 | 2.2 | 2.0 | 4.2 | 27 | \$.08 |
| 118 | 1.8 | 2.0 | 3.8 | 22 | \$.08 |
| 119 | 1.9 | 2.0 | 3.9 | 20 | \$.08 |
| 120 | 2.2 | 2.0 | 4.2 | 22 | \$.08 |
| 121 | 1.9 | 2.0 | 3.9 | 23 | \$.08 |
| 122 | 1.9 | 2.0 | 3.9 | 21 | \$.08 |
| 123 | 1.8 | 2.0 | 3.8 | 20 | \$.08 |
| 124 | 1.8 | 2.0 | 3.8 | 19 | \$.08 |
| 125 | 1.9 | 2.0 | 3.9 | 20 | \$.08 |
| 126 | 1.5 | 2.0 | 3.5 | 18 | \$.08 |
| 127 | 1.7 | 2.0 | 3.7 | 16 | \$.08 |
| 128 | 1.8 | 2.0 | 3.8 | 19 | \$.08 |
| 129 | 1.7 | 2.0 | 3.7 | 19 | \$.08 |
| 130 | 0.9 | 2.0 | 2.9 | 13 | \$.08 |
| 131 | 1.2 | 2.0 | 3.2 | 11 | \$.08 |
| 132 | 0.8 | 2.0 | 2.8 | 10 | \$.08 |
| 133 | 0.0 | 2.0 | 2.0 | 3 | \$.08 |
| | | | | 3243 | |
| | | | | | Totals |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *13- Main Line*

(8)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD | |
|------------------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|---------------------|
| Between Stake No. <i>133</i> | | | | <i>3243</i> | | |
| and Stake No. <i>134</i> | <i>0.0</i> | | | | | <i>In Deer Lake</i> |
| <i>135</i> | <i>0.0</i> | | | | | " " |
| <i>136</i> | <i>0.0</i> | | | | | " " |
| <i>137</i> | <i>0.0</i> | | | | | " " |
| <i>138</i> | <i>0.0</i> | | | | | " " |
| <i>139</i> | <i>0.0</i> | | | | | " " |
| <i>140</i> | <i>0.0</i> | | | | | " " |
| <i>141</i> | <i>0.6</i> | | | | | " " |
| <i>142</i> | <i>0.0</i> | | | | | " " |
| <i>143</i> | <i>0.0</i> | | | | | " " |
| <i>144</i> | <i>0.0</i> | | | | | " " |
| <i>145</i> | <i>0.0</i> | | | | | " " |
| <i>146</i> | <i>0.0</i> | | | | | " " |
| <i>147</i> | <i>0.0</i> | | | | | " " |
| <i>148</i> | <i>0.0</i> | | | | | " " |
| <i>149</i> | <i>0.0</i> | | | | | " " |
| <i>150</i> | <i>0.0</i> | | | | | " " |
| <i>151</i> | <i>0.0</i> | | | | | " " |
| <i>152</i> | <i>0.0</i> | | | | | " " |
| <i>153</i> | <i>0.0</i> | | | | | " " |
| <i>154</i> | <i>0.0</i> | | | | | " " |
| <i>155</i> | <i>0.0</i> | | | | | " " |
| <i>156</i> | <i>0.0</i> | | | | | " " |
| <i>157</i> | <i>0.0</i> | | | | | " " |
| <i>158</i> | <i>0.0</i> | | | | | " " |
| <i>159</i> | <i>0.0</i> | | | | | " " |
| <i>160</i> | <i>0.0</i> | | | | | " " |
| | | | | <i>3243</i> | | <i>Totals</i> |

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *13 Main Line* -

(10)

| SECTION | DEPTH OF CUT | WIDTH OF CUT AT BOTTOM | WIDTH OF CUT AT TOP | NO. OF CUBIC YARDS REMOVED | ESTIMATED COST PER CUBIC YARD | |
|------------------------------|--------------|------------------------|---------------------|----------------------------|-------------------------------|--------------------|
| Between Stake No. <i>179</i> | | | | <i>3243</i> | | |
| and Stake No. <i>180</i> | <i>0.0</i> | | | | | <i>In sur Lake</i> |
| <i>181</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>182</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>183</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>184</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>185</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>186</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>187</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>188</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>189</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>190</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>191</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>192</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>193</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>194</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>195</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>196</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>197</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| <i>198</i> | <i>0.0</i> | | | | | <i>" " "</i> |
| | | | | <i>3243</i> | | <i>Totals</i> |