

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

*Exhibit C of
Ditch 30*

No. 680.—Pioneer Press Co., St. Paul, Minn.

*Filed this 26th day of
March A.D. 1878*

*G. A. Putnam
Co. Auditor.
L.*

Handwritten notes in the left margin, including the number '30' and other illegible cursive text.

Large block of handwritten notes in the center of the page, containing several lines of cursive text.

Handwritten notes in the right margin, including the number '30' and other illegible cursive text.

TO THE
SECRETARY
AND
MEMBERS

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No. 30

SECTION	TIME WITHIN WHICH WORK MUST BE DONE	MANNER IN WHICH WORK MUST BE DONE	MATERIALS USED	COST OF MATERIALS AND WORK
State No. 0 TO State No. 51 Main line 0 to 12 of Branch	Dec 1 st 1898	All earth taken from ditch to be removed about two feet from edge of ditch branches.		
		Bridge at Sta 10+35 to consist of 2 bank piles and four stringers covered with 8" plank 3" x 12" x 16" spiked on bank piles and stringers to be around oak or better Larrea 12 ft long and not less than 5 in diameter.		
		Planks are put on Right hand edge of ditch.		