

Engineer's Report

IN

Ditch Proceedings.

cut out
EXHIBIT 2 OF ENGINEER'S REPORT IN DITCH PROCEEDINGS.

Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of Same, in *Repairs Co.* Ditch No. *32*

SECTION	(1)	(2)	(3)	No. Cu. Yds. (4) No. Cu. Yds.		(5)	(6)		(7)		
	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS TO BE REMOVED		Estimated Cost Per Cubic Yard	Character of Other Expenses, Including Preliminary Expenses And Expense of Inspecting Work until Completed With Total Per Section		Total Estimated Cost per Section		
				<i>Old Ditch</i>	<i>Excavated</i>	\$	CTS.	\$	CTS.	\$	CTS.
<i>cut out</i> Between Stake No. 1	2.5	2.0	7.0								
and Stake No. 2	2.4	"	6.8	19	22				15	3	30
Between Stake No. 3	2.9	"	7.8	22	24					3	60
and Stake No. 4	2.9	"	7.8	30	23					3	45
Between Stake No. 5	2.7	"	7.4	28	22					3	30
and Stake No. 6	2.7	"	7.4	26	21					3	15
Between Stake No. 7	3.1	"	8.2	24	29					4	35
and Stake No. 8	2.9	"	7.8	24	32					4	80
Between Stake No. 9	3.1	"	8.2	24	32					4	80
and Stake No. 10	3.1	"	8.2	24	35					5	25
Between Stake No. 11	3.2	"	8.4	26	34					5	10
and Stake No. 12	3.7	"	9.4	28	42					6	30
Between Stake No. 13	3.1	"	8.2	30	38					5	70
and Stake No. 14	3.4	"	8.8	30	33					4	95
Between Stake No. 15	3.5	"	9.0	30	40					6	00
and Stake No. 16	3.7	"	9.4	30	45					6	75
Between Stake No. 17	3.7	"	9.4	30	48					7	20
and Stake No. 18	4.2	"	10.4	30	57					8	55
				455	577					86	55

Amended Report Branch No 6 not to be dug

Total Estimated Cost of Whole Work, \$.....