

EXHIBIT I.

VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

Ditch No 32

Branch No 5

Estimated Cost

= \$9408

No. 686.— Pioneer Press Co., St. Paul, Minn.

Filed July 11th 1898

J. M. Putnam
County Auditor

6 11

6 37

2 80

15 6

11 11

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *32 Branch 5*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
<i>Between Stake No. 0</i>	<i>2.1</i>	<i>2 1/2</i>	<i>5.1</i>		<i>V</i>
<i>and Stake No. 1</i>	<i>2.3</i>		<i>5.4</i>	<i>30</i>	
<i>2</i>	<i>2.5</i>		<i>5.7</i>	<i>34</i>	
<i>3</i>	<i>2.6</i>		<i>5.9</i>	<i>37</i>	
<i>4</i>	<i>2.5</i>		<i>5.7</i>	<i>37</i>	
<i>5</i>	<i>2.6</i>		<i>5.9</i>	<i>37</i>	
<i>6</i>	<i>2.8</i>		<i>6.2</i>	<i>40</i>	
<i>7</i>	<i>2.5</i>		<i>5.7</i>	<i>39</i>	
<i>8</i>	<i>2.6</i>		<i>5.9</i>	<i>37</i>	
<i>9</i>	<i>2.8</i>		<i>6.2</i>	<i>40</i>	
<i>10</i>	<i>2.9</i>	<i>6.3</i>	<i>44</i>	<i>V</i>	
<i>1</i>	<i>2.8</i>	<i>6.2</i>	<i>44</i>		
<i>2</i>	<i>2.8</i>	<i>6.2</i>	<i>43</i>		
<i>3</i>	<i>2.8</i>	<i>6.2</i>	<i>43</i>		
<i>4</i>	<i>2.5</i>	<i>5.7</i>	<i>39</i>		
<i>5</i>	<i>2.5</i>	<i>5.7</i>	<i>36</i>		
<i>6</i>	<i>1.4</i>	<i>4.1</i>	<i>26</i>		
<i>7</i>	<i>1.2</i>	<i>3.8</i>	<i>14</i>		
<i>8</i>	<i>1.2</i>	<i>3.8</i>	<i>13</i>		
<i>9</i>	<i>1.3</i>	<i>3.9</i>	<i>14</i>		
			<i>647</i>	<i>9 1/2</i>	
<i>Totals</i>					

Add 161 cubic yards

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *37 Branch No 5*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <i>20</i>	<i>1.8</i>	<i>2 ft</i>	<i>4.7</i>	<i>18</i>	<i>All dirt (6) Carted by Dwyer</i>
and Stake No. <i>1</i>	<i>3.1</i>		<i>6.6</i>	<i>35</i>	
<i>2</i>	<i>3.4</i>	"	<i>7.1</i>	<i>53</i>	
<i>3</i>	<i>3.2</i>	"	<i>6.8</i>	<i>55</i>	
<i>4</i>	<i>2.9</i>	"	<i>6.3</i>	<i>37</i>	
<i>5</i>	<i>2.2</i>	"	<i>5.3</i>	<i>37</i>	
<i>6</i>	<i>1.8</i>	"	<i>4.7</i>	<i>26</i>	
<i>7</i>	<i>1.8</i>	"	<i>4.7</i>	<i>23</i>	
<i>8</i>	<i>1.5</i>	"	<i>4.3</i>	<i>20</i>	
<i>9</i>	<i>2.4</i>	"	<i>5.6</i>	<i>25</i>	
<i>30</i>	<i>3.1</i>	"	<i>6.6</i>	<i>41</i>	
<i>1</i>	<i>2.8</i>	"	<i>6.2</i>	<i>46</i>	
<i>2</i>	<i>2.7</i>	"	<i>6.0</i>	<i>41</i>	
<i>3</i>	<i>2.5</i>	"	<i>5.7</i>	<i>38</i>	
<i>4</i>	<i>1.8</i>	"	<i>4.7</i>	<i>29</i>	
<i>5</i>	<i>1.8</i>	"	<i>4.7</i>	<i>23</i>	
<i>6</i>	<i>1.7</i>	"	<i>4.5</i>	<i>22</i>	
<i>7</i>	<i>1.5</i>	"	<i>4.3</i>	<i>19</i>	
<i>8</i>	<i>1.6</i>	"	<i>4.4</i>	<i>18</i>	
<i>9</i>	<i>1.6</i>	"	<i>4.4</i>	<i>19</i>	
				<i>639</i>	<i>7 1/2</i>
				<i>9</i>	
					<i>Totals</i>

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. *32 Branch No 5*

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD	
Between Stake No. <i>40</i>	<i>1.6</i>	<i>2 1/2 ft</i>	<i>4.4</i>	<i>19</i>	<i>All dirt (6) cut for you</i>	
and Stake No. <i>1</i>	<i>1.6</i>		<i>4.4</i>	<i>19</i>		
<i>2</i>	<i>1.7</i>	<i>"</i>	<i>4.5</i>	<i>20</i>		
<i>3</i>	<i>1.7</i>		<i>4.5</i>	<i>22</i>		
<i>4</i>	<i>1.7</i>	<i>"</i>	<i>4.5</i>	<i>22</i>		
<i>5</i>	<i>2.1</i>		<i>5.1</i>	<i>25</i>		
<i>6</i>	<i>2.2</i>	<i>"</i>	<i>5.3</i>	<i>29</i>		
<i>7</i>	<i>1.9</i>		<i>4.8</i>	<i>27</i>		
<i>8</i>	<i>1.9</i>	<i>"</i>	<i>4.8</i>	<i>25</i>		
<i>9</i>	<i>2.0</i>		<i>5.0</i>	<i>25</i>		
<i>50</i>	<i>2.3</i>	<i>"</i>	<i>5.4</i>	<i>29</i>	<i>Estimate Branch No 5 1528 yds Ex @ 6 = 9168</i>	
<i>70</i>	<i>2.0</i>		<i>5.0</i>	<i>20</i>		
<i>146</i>				<i>(12)</i>		
				<i>7 1/2</i>		
				<i>28 2/3</i>		Totals