

EXHIBIT I.

---

# VIEWERS' REPORT

—IN—

DITCH PROCEEDINGS.

---

*Ditch No 32*

*Branch No 14*

*Estimated Cost*

*= \$17196*

---

No. 686.—Pioneer Press Co., St. Paul, Minn.

*Filed July 11<sup>th</sup> 1898*

*J. W. Putnam*  
*County Auditor*

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 14

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>0</u>	<u>2.1</u>	<u>2 ft</u>	<u>5.1</u>		✓
and Stake No. <u>1</u>	<u>2.3</u>		<u>5.4</u>	<u>30</u>	✓
<u>2</u>	<u>2.8</u>		<u>6.2</u>	<u>37</u>	✓
<u>3</u>	<u>2.5</u>		<u>5.7</u>	<u>39</u>	✓
<u>4</u>	<u>2.6</u>		<u>5.9</u>	<u>37</u>	✓
<u>5</u>	<u>2.4</u>		<u>5.6</u>	<u>36</u>	✓
<u>6</u>	<u>2.8</u>		<u>6.2</u>	<u>38</u>	✓
<u>7</u>	<u>2.1</u>		<u>5.1</u>	<u>35</u>	✓
<u>8</u>	<u>2.0</u>		<u>5.0</u>	<u>27</u>	✓
<u>9</u>	<u>2.0</u>		<u>5.0</u>	<u>26</u>	✓
<u>10</u>	<u>2.3</u>		<u>5.4</u>	<u>29</u>	✓
<u>11</u>	<u>2.6</u>		<u>5.9</u>	<u>30</u>	✓
<u>12</u>	<u>3.0</u>		<u>6.5</u>	<u>20</u>	✓
<u>13</u>	<u>3.4</u>		<u>7.1</u>	<u>23</u>	✓
<u>14</u>	<u>2.5</u>		<u>5.7</u>	<u>21</u>	✓
<u>15</u>	<u>3.7</u>		<u>7.5</u>	<u>20</u>	✓
<u>16</u>	<u>2.7</u>		<u>6.0</u>	<u>12</u>	✓
<u>17</u>	<u>2.0</u>		<u>5.0</u>	<u>10</u>	✓
<u>18</u>	<u>1.9</u>		<u>4.8</u>	<u>14</u>	✓
<u>19</u>	<u>2.2</u>	<u>5.3</u>	<u>16</u>	✓	
			<u>500</u>		9/10
			<u>8</u>		
<i>Totals</i>					

All Run Cuttop yr

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 14

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>20</u>	<u>2.6</u>	<u>2 ft</u>	<u>5.9</u>	<u>23</u>	<u>All Eight (8) Cents per yd</u>
and Stake No. <u>1</u>	<u>2.2</u>		<u>5.3</u>	<u>23</u>	
<u>2</u>	<u>3.3</u>		<u>6.9</u>	<u>27</u>	
<u>3</u>	<u>3.0</u>		<u>6.5</u>	<del>25</del> <u>25</u>	
<u>4</u>	<u>3.0</u>		<u>6.5</u>	<u>26</u>	
<u>5</u>	<u>3.2</u>		<u>6.8</u>	<u>27</u>	
<u>6</u>	<u>3.0</u>	<u>6.5</u>	<u>26</u>		
<u>7</u>	<u>3.3</u>	<u>6.9</u>	<u>27</u>		
<u>8</u>	<u>4.2</u>	<u>3 ft</u>	<u>9.3</u>	<u>45</u>	
<u>9</u>	<u>4.2</u>		<u>9.3</u>	<u>59</u>	
<u>10</u>	<u>4.6</u>		<u>9.9</u>	<u>54</u>	
<u>11</u>	<u>5.1</u>	<u>10.6</u>	<u>57</u>		
<u>12</u>	<u>5.4</u>	<u>11.0</u>	<u>65</u>		
<u>13</u>	<u>4.0</u>	<u>9.0</u>	<u>45</u>		
<u>14</u>	<u>3.1</u>	<u>2 ft</u>	<u>6.6</u>	<u>20</u>	
<u>15</u>	<u>2.9</u>		<u>6.3</u>	<u>14</u>	
<u>16</u>	<u>2.2</u>		<u>5.3</u>	<u>30</u>	
<u>17</u>	<u>2.1</u>		<u>5.1</u>	<u>20</u>	
<u>18</u>	<u>1.8</u>		<u>4.7</u>	<u>18</u>	
<u>19</u>	<u>1.7</u>	<u>4.5</u>	<u>17</u>		
			<u>648</u>	<u>10 1/2</u>	
<i>Totals</i>					

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 14

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>40</u>	<u>1.5</u>	<u>2 ft</u>	<u>4.3</u>	<u>15</u>	<u>10 3/10</u>
and Stake No. <u>1</u>	<u>2.0</u>		<u>5.0</u>	<u>18</u>	
<u>2</u>	<u>1.5</u>	"	<u>4.3</u>	<u>17</u>	
<u>3</u>	<u>1.5</u>		<u>4.3</u>	<u>13</u>	
<u>4</u>	<u>2.2</u>	"	<u>5.0</u>	<u>18</u>	
<u>5</u>	<u>2.0</u>		<u>5.0</u>	<u>20</u>	
<u>6</u>	<u>1.8</u>	"	<u>4.7</u>	<u>18</u>	
<u>7</u>	<u>1.8</u>		<u>4.7</u>	<u>17</u>	
<u>8</u>	<u>2.4</u>	"	<u>5.6</u>	<u>19</u>	
<u>+ 50</u>	<u>3.2</u>		<u>6.8</u>	<u>11</u>	
<u>9</u>	<u>2.4</u>	"	<u>5.6</u>	<u>26</u>	
<u>50</u>	<u>2.6</u>		<u>5.9</u>	<u>25</u>	
<u>1</u>	<u>2.5</u>	"	<u>5.7</u>	<u>21</u>	
<u>2</u>	<u>2.6</u>		<u>5.9</u>	<u>20</u>	
<u>3</u>	<u>2.7</u>	"	<u>6.0</u>	<u>20</u>	
<u>4</u>	<u>1.9</u>		<u>4.8</u>	<u>16</u>	
<u>5</u>	<u>3.4</u>	"	<u>7.1</u>	<u>21</u>	
<u>6</u>	<u>2.7</u>		<u>6.0</u>	<u>24</u>	
<u>7</u>	<u>3.0</u>	"	<u>6.5</u>	<u>23</u>	
<u>8</u>	<u>3.0</u>		<u>6.5</u>	<u>25</u>	
				<u>376</u>	
					<i>All Eight (8) Centeforg</i>
					<i>Totals</i>

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 14

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>59</u>	<u>3.3</u>	<u>2 ft</u>	<u>6.9</u>	<u>25</u>	<u>All Eight (8) Centajen ya</u>
and Stake No. <u>60</u>	<u>3.3</u>		<u>6.9</u>	<u>28</u>	
<u>1</u>	<u>3.7</u>	"	<u>7.5</u>	<u>26</u>	
<u>2</u>	<u>3.4</u>	"	<u>7.1</u>	<u>25</u>	
<u>3</u>	<u>3.3</u>	"	<u>6.9</u>	<u>27</u>	
<u>4</u>	<u>2.1</u>	"	<u>5.1</u>	<u>21</u>	
<u>5</u>	<u>2.7</u>	"	<u>6.0</u>	<u>19</u>	
<u>6</u>	<u>1.9</u>	"	<u>4.8</u>	<u>20</u>	
<u>7</u>	<u>2.0</u>	"	<u>5.0</u>	<u>15</u>	
<u>+40</u>	<u>3.5</u>	"	<u>7.2</u>	<u>20</u>	
<u>8</u>	<u>2.4</u>	"	<u>5.2</u>	<u>29</u>	
<u>9</u>	<u>2.7</u>	"	<u>6.0</u>	<u>25</u>	
<u>70</u>	<u>2.7</u>	"	<u>6.0</u>	<u>26</u>	
<u>1</u>	<u>2.9</u>	"	<u>6.3</u>	<u>28</u>	
<u>+40</u>	<u>3.3</u>	"	<u>6.9</u>	<u>20</u>	
<u>2</u>	<u>2.6</u>	"	<u>5.4</u>	<u>28</u>	
<u>3</u>	<u>3.3</u>	"	<u>6.9</u>	<u>22</u>	
<u>4</u>	<u>3.1</u>	"	<u>6.6</u>	<u>26</u>	
<u>5</u>	<u>2.9</u>	"	<u>6.3</u>	<u>32</u>	
<u>6</u>	<u>3.1</u>	"	<u>6.6</u>	<u>35</u>	
				<u>457</u>	<u>10 4/10</u>
				<u>9</u>	
					<i>Totals</i>

EXHIBIT 1 OF VIEWERS' REPORT IN DITCH PROCEEDINGS, Showing Estimated Depth of Cut, Width, No. of Cubic Yards Removed and Cost of same, in Ditch No. 32 Branch 14

SECTION	DEPTH OF CUT	WIDTH OF CUT AT BOTTOM	WIDTH OF CUT AT TOP	NO. OF CUBIC YARDS REMOVED	ESTIMATED COST PER CUBIC YARD
Between Stake No. <u>77</u>	<u>3.1</u>	<u>2 ft</u>	<u>6.6</u>	<u>37</u>	✓
and Stake No. <u>8</u>	<u>3.3</u>		<u>6.9</u>	<u>37</u>	
<u>9</u>	<u>3.6</u>	<u>"</u>	<u>7.4</u>	<u>41</u>	✓
<u>80</u>	<u>3.7</u>		<u>7.5</u>	<u>44</u>	✓
<u>1</u>	<u>3.7</u>	<u>"</u>	<u>7.5</u>	<u>40</u>	✓
<u>+90</u>	<u>3.7</u>		<u>7.5</u>	<u>32</u>	✓ <u>10 1/2</u>
				<u>232</u>	
<p><i>All Eight (8) Cuts per year</i>  <i>Estimated Branch no 14</i>  <u>1712 yds @ 8¢ = 136.96</u>  <u>500 " " 7 " = 35.00</u>  <u>Polite = \$171.96</u></p>					
					<i>Totals</i>