ENGINEER'S REPORT

IN

DITCH PROCEEDINGS.

Tilsel July 21th 1902 Selden M. Lappy Co. andethir

Exhibit 2 of Engineer's Report in Ditch Proceedings.

Showing Time and Manner in which same must be done. Ditch No.

Stake No To Stake No	Stake Noro Stake No	Stake Noro Stake No	Stake No	Stake Noro Stake No	Stake Noro Stake No	Stake No. 0 Stake No. 179+16	SECTION	Showing
						Junu 12/903	TIME WITHIN WHICH WORK MUST BE DONE	Time and Manner
						All gath to be throw two 2 fest from eage ways the enquel.	MANNER IN WHICH WORK MUST BE DONE	" in which same must be done.
					3)	noted by	MATERIALS USED	Ditch No.
							COST OF MATERIALS AND WORK	