

It appears that portions of 32 were rebuilt and included in 53 and similarly portions of 32 & 53 were rebuilt and included in 62.

①

②

Cost of County Ditches #32, #53, #62

Original Ditch #32 Cost Statement Filed Nov. 7, 1898 (Excavation @ 7¢)	6439.02		1
Repairs Ditch #32 Contract Dated Nov. 26, 1915 (\$12,746.60) Filed Dec. 12, 1916 (Exc. @ 15¢)	14562.08		2
Ditch #53 Cost Statement Filed July 18, 1911 (Excavation @ 10¢ @ 12¢)	38619.22		3
Repairs Ditch #53 Cost Statement Filed Aug 14, 1917 (Excavation @ 15¢)	11064.49		4
Ditch #62 Cost Statement Filed Dec 20, 1918 (Excavation @ 15¢)	12136.57	77821.38	5

Length of Main Ditch Lying West of
Elwell Grade running south from crossing
point in Sections 13 & 14 & 23 & 26 & 25:

Ditch #53

440
830
1270'

Each 1' of a uniform clean-
out on an 8' bottom
figures 3425 c.y.

470
3580
3070

Ditch #62

Brushing @ 3' 2" 6.37 A.

1990
680
150
1350
10290'

11560'

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40