CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


County of Anoka


State of Minnesota

Northeast Corner of Sec. 36 Township 32 Range 24

On t	he <u>13th</u> day of <u>September</u> , <u>1960</u> , the described corner was evidenced by <u>a granite</u>
<u>mon</u>	ument
and	to perpetuate the location of said corner, at the exact location thereof, a permanent marke
was	placed consisting of <u>a cast iron monument</u>
AND	on the <u>31st</u> day of <u>January</u> , <u>2011</u> , said permanent marker was <u>found and the ties</u>
were	updated

Updated reference ties are as shown below.





N.A.D. 1983 Coordinates (1996 Adjustment)

County F	Project Coordinates
Northing	169613.6568
Easting	500278.2289
Date	11/19/01

I hereby certify that this United States public land survey monument record is correct and complete to the best of my knowledge and belief.

Larry D. Hoium , Anoka County Surveyor

Minnesota License Number

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


County of Anoka


State of Minnesota

Northeast Corner of Sec. 36 Township 32 Range 24

On t	he <u>13th</u> day of <u>September</u> , <u>1960</u> , the described corner was evidenced by <u>a granite</u>
<u>mon</u>	ument
and	to perpetuate the location of said corner, at the exact location thereof, a permanent marke
was	placed consisting of <u>a cast iron monument</u>
AND	on the <u>31st</u> day of <u>January</u> , <u>2011</u> , said permanent marker was <u>found and the ties</u>
were	updated

Updated reference ties are as shown below.





N.A.D. 1983 Coordinates (1996 Adjustment)

County F	Project Coordinates
Northing	169613.6568
Easting	500278.2289
Date	11/19/01

I hereby certify that this United States public land survey monument record is correct and complete to the best of my knowledge and belief.

Larry D. Hoium , Anoka County Surveyor

Minnesota License Number

Page No. 120

HISTORY OF GOVERNMENT CORNER

County of Anoka

State of Minnesota

Northeast Corner of Sec. 36 Township 32 Range 24

CORNER HISTORY:

Unable to locate field notes prior to November 19, 2001.

November 19, 2001 - Found corner monument missing due to construction. Reset position of corner with a cast iron monument using area resurvey and verified position by Static GPS methods.

January 31, 2011 - Found cast iron monument and updated ties.