

CERTIFICATE OF ANOKA COUNTY BENCHMARK LOCATION

County of Anoka

State of Minnesota

Located in the SW 1/4 of

Section 23 Township 33 Range 25

Horizontal Location

Vertical Location


N.A.D. 1983 Coordinates County Project Coordinates
Northing <u>209303</u>
Easting <u>461021</u>
(1996 Adjustment)

National Geodetic Vertical Datum
Elevation <u>914.741</u> (1929 Adjustment)

North American Vertical Datum
Elevation <u>915.000</u> (1988 Adjustment)

Description:

Railroad spike in the North face of a 30 inch Oak Tree. The tree has almost overgrown the spike as there is not much left visible. The horizontal location shown is approximately 14 feet North of the actual location.



Previous Benchmark ID <u>GREEN 58</u>
Reference Bench Loop <u>FRANCIS</u>
Bench Loop Point No. <u>343</u>
Anoka County Surveyor (ACS) No. <u>NA</u>

Last Revised
02/05/13

Date Set <u>05/28/1995</u>
Warning Sign Set <u>No</u>
Last Visited <u>12/20/12</u>
Condition <u>Moderate</u>