

Profile Sitch No. 13
Main line

Filed March 30th 1891.
W. W. Putnam
Geo Auditor

100

95

90

0


10

20

30

40


50




*Profile
of
Ditch No.13.
-Main Line-
-1891-*


94.0


Grass Lake.




Deer Lake.







Crooked Brook



Profile
of
Ditch No. 13.
-Main Line-
1891.

