

**ANOKA COUNTY**  
**COUNTY DITCH INSPECTION REPORT**

**DITCH # 19**

**DATE: 7/15/94**

**BY: P K Ruud**


**COMMUNITIES: Oak Grove, St. Francis**

**REMARKS:**

Tulip St	Ditch well defined and flowing freely.
206th Ave	Ditch defined, marsh on both sides of road. Ditch flowing.
CSAH # 9	Ditch well-defined and flowing both north and south of 202nd.
CSAH # 9	Outlet from Hickey Lake. Ditch well defined and flowing. Marsh ( open water ) to east and west.
Heather St	Ditch well defined and flowing.
201st Ave	Ditch well defined and flowing.
CR # 67	Ditch well defined and flowing. Branch ditch connection to Lake George about 1/4 mile downstream.
221st Ave	Ditch well maintained, no apparent flow. Active peatland farming to north and south.
CR # 103	At west crossing the ditch is not noticeable. Overgrown marsh. Peatland farming to north and south.
CR # 103	At east crossing the ditch is well maintained. No apparent flow.
CSAH # 24	At east crossing the ditch is overgrown with grass. No apparent flow. Peatland farming to south.
CSAH # 24	At west crossing the ditch is defined on the south side. Marsh land on both sides of road.

**ACTIVITIES:**

Maintenance of the branch ditch connecting Lake George to Ditch # 19 is a problem from time to time. There are no funds for maintenance to ensure the ditch is cleaned so it can work. This branch provides both an outlet and a possible inlet for the lake, depending on water levels.



CO DIT #19