

**ANOKA COUNTY**  
**COUNTY DITCH INSPECTION REPORT**

**DITCH # 21 (AKA # 71)**

**DATE: 7/7/94**

**BY: P K Ruud**

**COMMUNITIES: Andover, Ham Lake, Oak Grove**

**REMARKS:**

CR # 58 (181st Ave) Ditch well defined and flowing well.

CR # 78 Ditch well defined and flowing well. Ditch maintained by peatland farmers from west of CR # 78, east to the BN Railroad tracks.


Ward Lake Dr Ditch well maintained and flowing.

CR # 58 (Palm St) Ditch well defined and flowing. There is a walking bridge across the ditch to the west that appears to be about 4' above the water level of the ditch.

University Ext This road stops at a temporary cul-de-sac south of the ditch.

**ACTIVITIES:**

The county was named in a law suit several years ago because of a snowmobile accident. The accident occurred just west of the BN Tracks. Plaintiff's name was Steinke.



**CO DIT #21**