ANOKA COUNTY

COUNTY DITCH INSPECTION REPORT

DITCH # 35

DATE: 7/8/94

BY: P K Ruud

COMMUNITIES: Columbus

REMARKS:

181st Ave

Ditch defined on the south side of the road, overgrown on the north

side. No apparent flow.

Xingu St

Ditch overgrown, no visible flow.

179th Ave

Ditch overgrown, no visible flow.

Ussuri St

Ditch defined and flowing to the east. (This street is identified as

Ural St on the map.)

MacKenzie St

Ponds dug on both sides of the road. Flow to the east.

CSAH # 18

Well defined wide ditch. Flow to the north.

DNR Road

Clear ditch, with overflow structure on the west side of the road.

Good flow to the east. Pool Elevation on west side-7.00' (Gage

Reading.)

ACTIVITIES:

