ANOKA COUNTY

COUNTY DITCH INSPECTION REPORT

DITCH #36

DATE: 7/13/94

BY: PK Ruud

COMMUNITIES: East Bethel

REMARKS:

Klondike Road

Ditch faintly discernible, overgrown with brush and canary grass.

No apparent flow.

Private Road

(1/2 mile north of # 22) Ditch along west side of T H # 65

maintained and some flow to the south.

Ditch west 0.1 mile defined and maintained. No apparent flow.

Both of these ditches are connected.

CSAH # 22


Ditch along west side of T H 65 defined and flowing well.

Note: As a part of the overlay and culvert repair project being done by MN/DOT, the culvert that carries DITCH #36 under CSAH # 22 will be replaced by MN/DOT at their expense. (See the Public Works Committe Report for the August 1, 1994

meeting.)

ACTIVITIES:

Active peatland farming on 40 acres north of and 40 acres south of the above noted private road.



#36

7/13/94

PKL

Klondike Rd.

Ditch family discernible grown over with brush &
canary grass - no apparent
flow.

Private Rd. (1/2 mi. N. of #22) Ditch along west side of TH 65 maintained and same flow to south.

Ditch west 0.1 mi, defined & maintained - no affarent flow.

Both of these ditches are connected.

Active peatland farming on 40 Ac. on north side and on 40 Ac. on south side.

#22

Ditch, along west side of TH 65 defined & flowing to south.

PUBLIC DRAINAGE DITCH INVENTORY FORM (Laws of 1990, Chapter 601, Section 27)

1. Drainage authority name: Anoka County (East Bethel)	
2. Drainage ditch name and number: #36	
3. Ditch location and drainage area boundary: (shown on attached quadrangle map)	
4. Drainage area in acres: 840; Benefitted area in acres: 258	
5. Approximate length in miles: Open Ditch 2.65 Buried Tile 0	
6. Year constructed: 1899; Original cost: \$ 611.30	
7. Are original plans on file? Yes X No; Location: Anoka County County	rthou
8. Date of original plans: 1899	
9. Are "as built" plans on file? Yes Nox ; Location:	
10. Year(s) improved: None	
11. Are improvement plans on file? Yes NoN/A; Location:	
12. Year(s) repaired: None	
13. Are repair plans on file? Yes No _ x ; Location:	
14. If the ditch was transferred from a county or joint county ditch authority to a watersh district or WMO, is the transfer order on file? Yes No _x NA	ied
15. Is the list of lands benefitted and damaged on file? Yes X No	
16. Have the benefits and damages been redetermined? Yes NoX; If yes, year of redetermination:	·(s)
17. Has right-of-way been acquired for a 1-rod permanent grassed strip? Yes No _X_ ; If yes, has it been maintained? Yes No _N/A	
18. Is there a maintenance fund for the ditch? Yes No _x ; If yes, current balar in maintenance fund: \$	nce
19. What was the last year maintenance work was performed by drainage author unknown	ity:

se

PUBLIC DRAINAGE DITCH INVENTORY FORM (Laws of 1990, Chapter 601, Section 27)

1. Drainage authority name: Anoka County (East Bethel)
2. Drainage ditch name and number: #36
3. Ditch location and drainage area boundary: (shown on attached quadrangle map)
4. Drainage area in acres: 840; Benefitted area in acres: 258
5. Approximate length in miles: Open Ditch 2.65 Buried Tile 0
6. Year constructed: 1899; Original cost: \$ 611.30
7. Are original plans on file? Yes _ x No ; Location: _Anoka County Courthou
8. Date of original plans:
9. Are "as built" plans on file? Yes Nox ; Location:
10. Year(s) improved: None
11. Are improvement plans on file? Yes NoN/A; Location:
12. Year(s) repaired: None
13. Are repair plans on file? Yes Nox ; Location:
14. If the ditch was transferred from a county or joint county ditch authority to a watershed district or WMO, is the transfer order on file? Yes No _x NA
15. Is the list of lands benefitted and damaged on file? Yes X No
16. Have the benefits and damages been redetermined? Yes No; If yes, year(s) of redetermination:
17. Has right-of-way been acquired for a 1-rod permanent grassed strip? Yes NoX ; If yes, has it been maintained? Yes No _N/A
18. Is there a maintenance fund for the ditch? Yes No _x ; If yes, current balance in maintenance fund: \$
19. What was the last year maintenance work was performed by drainage authority:unknown

