

# ANOKA COUNTY

## COUNTY DITCH INSPECTION REPORT

**DITCH # 42**

**DATE: 7/18/94**

**BY: P K Ruud**

**COMMUNITIES: Burns**

**REMARKS:**


Xenon St	Good flow to the east thru a well defined ditch. Ekstrom Lake abuts the west side of the street.
Pinnaker Road	Ditch well defined and flowing. Tree laying in the ditch, in water, east of the road. Other trees and brush over-hanging the ditch.
Basalt Street	Ditch defined but overgrown with canary grass. Some use of meadow on each side of the road for hay.

**ACTIVITIES:**

Ditch # 42 is the outlet for Goose Lake which receives drainage from Ditch # 49. Over the past 15 years, floating bogs on Goose Lake have moved to the north-east end of the lake and plugged the outlet.

In one instance, the DNR Conservation Officer was able to work on the bog and get some relief.

Approval to install 2-60" diameter or 2- 71"x47" arch pipe was given to Lee & Deb Lindahl in June, 1994 in the ditch in the S1/2 SW1/4 NW1/4 Section 11, T 33, R25 for a field crossing.



**CO DIT #42**