

ANOKA COUNTY
COUNTY DITCH INSPECTION REPORT

DITCH # 48

DATE: 7/7/94


BY: P K Ruud

COMMUNITIES:Oak Grove

REMARKS:

- C R # 78 (Flamingo St) Ditch defined in a deep channel but overgrown with grass and brush. Ditch is flowing.
- C R # 67 (Cedar Dr) Ditch defined and flowing. Trees laying in the ditch to the west.
- Swan Lk Dr (West) Ditch defined and flowing.
- Swan Lk Dr (East) Ditch on north side is defined. On the south side, a pond has been excavated in a marsh area. The ditch is visible further south but in poor repair.

ACTIVITIES:



C.R. #78









#48

#48

C.R. #67

#48

CO DIT #48



1833
1834
1835
1836
1837
1838
1839
1840
1841
1842
1843
1844
1845
1846
1847
1848
1849
1850
1851
1852
1853
1854
1855
1856
1857
1858
1859
1860
1861
1862
1863
1864
1865
1866
1867
1868
1869
1870
1871
1872
1873
1874
1875
1876
1877
1878
1879
1880
1881
1882
1883
1884
1885
1886
1887
1888
1889
1890
1891
1892
1893
1894
1895
1896
1897
1898
1899
1900