

EXHIBIT 2 OF VIEWERS' REPORT IN DITCH PROCEEDINGS.

Showing Time and Manner in which same must be done. Ditch No.

SECTION	TIME WITHIN WHICH WORK MUST BE DONE	MANNER IN WHICH WORK MUST BE DONE	MATERIALS USED	COST OF MATERIALS AND WORK
Stake No. 0 To 110 Stake No. 110 Main Side	July 10 th 1890	Carts to be removed at least one foot from edge of ditch		
Sta 0 To Sta 45 Side B	July 10 th 1890	"		
Sta 110 To Sta 245 Main line	Dec 14 th 1889	"		
Sta 0 To Sta 140 A Side	July 10 th 1890	"		
Sta 0 To Sta 112 E Side	July 10 th 1890	"		