



← DATE, TIME, LIGHT, WEATHER

- ☒ OVERTURN
- 🔥 FIRE OR EXPLOSION
- MOVING VEHICLE
- ← REAR END
- ↔ BACKING VEHICLE
- ☐ COLLISION WITH FIXED OBJECT
- ↔ SIDE SWIPE SAME DIRECTION
- ↔ SIDE SWIPE OPPOSITE DIRECTION

- 🚗 PARKED VEHICLE
- 🏍️ MOTORCYCLE
- 🦌 DEER
- 🚶 PEDESTRIAN
- 🚲 BICYCLE
- ☐ FIXED OBJECT
- ↔ RIGHT ANGLE

- 🌀 VEHICLE OUT OF CONTROL
- ↔ LEFT TURN INTO ONCOMING TRAFFIC



**ANOKA COUNTY  
HIGHWAY DEPT.**

ADT:  
ACCIDENT RATE:  
SEVERITY RATE:

CR INDEX:  
FAR INDEX:

**COLLISION  
DIAGRAM**

CSAH 116 (BUNKER LAKE BLVD)  
@ 38TH AVE  
JANUARY 2018 - JUNE 2023

Sheet   1   of   1   Sheets

**LIGHT**

L = LIGHT  
DN = DAWN  
DU = DUSK  
D = DARK  
X = UNKNOWN

**WEATHER**

C = CLEAR  
CL = CLOUDY  
R = RAIN  
S = SNOW/SLEET  
X = OTHER/UNKNOWN

**SEVERITY CODE**

(N) PROPERTY DAMAGE  
(C) POSSIBLE INJURY  
(B) MINOR INJURY  
(A) SERIOUS INJURY  
(K) FATALITY