






ACCIDENT LOCATIONS ARE APPROXIMATE













UTILITY POLE

 \square N \square QQ

01/01/19 (8-9 PM) D, C

CSAH 17 (197TH AVE)

COON LAKE MAINTENANCE SHOP

ACCIDENT LOCATIONS ARE APPROXIMATE

DU = DUSK

D = DARK

X = UNKNOWN

SEVERITY CODE **WEATHER** LIGHT C = CLEAR N PROPERTY DAMAGE L = LIGHT DN = DAWN

DATE, TIME, LIGHT, WEATHER

CL = CLOUDY R = RAIN S = SNOW/SLEET X = OTHER/UNKNOWN

© POSSIBLE INJURY B MINOR INJURY

A SERIOUS INJURY


K FATALITY

♠ FIRE OR EXPLOSION - MOVING VEHICLE --- REAR END →→→→ BACKING VEHICLE □--- COLLISION WITH FIXED OBJECT

NOVERTURN

SIDE SWIPE SAME DIRECTION

■ Continue of the continue of SIDE SWIPE OPPOSITE DIRECTION



☐ FIXED OBJECT RIGHT ANGLE

ANOKA COUNTY


▼ VEHICLE OUT OF CONTROL LEFT TURN INTO ONCOMING TRAFFIC

ADT: 1603 - CORRIDOR ACCIDENT RATE: 0.49 CR INDEX: 0.81 SEVERITY RATE: 0.81 FAR INDEX: 0.00

ANOKA COUNTY HIGHWAY DEPT. DIAGRAM

CSAH 17 (197TH AVE) **COLLISION** JAN 2014 TO JUNE 2024

Sheet 11 of 12 Sheets



LIGHT

L = LIGHT

DN = DAWN

DU = DUSK

D = DARK

X = UNKNOWN