



← DATE, TIME, LIGHT, WEATHER

- ☒ OVERTURN
- 🔥 FIRE OR EXPLOSION
- MOVING VEHICLE
- ← REAR END
- ↔ BACKING VEHICLE
- ☐ COLLISION WITH FIXED OBJECT
- ↔ SIDE SWIPE SAME DIRECTION
- ↔ SIDE SWIPE OPPOSITE DIRECTION

- 🚗 PARKED VEHICLE
- 🏍️ MOTORCYCLE
- 🦌 DEER
- 🚶 PEDESTRIAN
- 🚲 BICYCLE
- ☐ FIXED OBJECT
- ↔ RIGHT ANGLE

- 🌀 VEHICLE OUT OF CONTROL
- ↔ LEFT TURN INTO ONCOMING TRAFFIC



**ANOKA COUNTY
HIGHWAY DEPT.**

ADT: 7978
ACCIDENT RATE: 0.55 CR INDEX: 1.57
SEVERITY RATE: 0.76 FAR INDEX: 1.06

**COLLISION
DIAGRAM**

CSAH 22 (Viking Blvd) @
CSAH 78 (Flamingo St)
2018 to 2022

LIGHT

L = LIGHT
DN = DAWN
DU = DUSK
D = DARK
X = UNKNOWN

WEATHER

C = CLEAR
CL = CLOUDY
R = RAIN
S = SNOW/SLEET
X = OTHER/UNKNOWN

SEVERITY CODE

○ PROPERTY DAMAGE
⊙ POSSIBLE INJURY
⊕ MINOR INJURY
⊖ SERIOUS INJURY
● FATALITY