



Gillis St

DATE, TIME, LIGHT, WEATHER

- OVERTURN
- FIRE OR EXPLOSION
- MOVING VEHICLE
- REAR END
- BACKING VEHICLE
- COLLISION WITH FIXED OBJECT
- SIDE SWIPE SAME DIRECTION
- SIDE SWIPE OPPOSITE DIRECTION
- PARKED VEHICLE
- MOTORCYCLE
- DEER
- PEDESTRIAN
- BICYCLE
- FIXED OBJECT
- RIGHT ANGLE
- VEHICLE OUT OF CONTROL
- LEFT TURN INTO ONCOMING TRAFFIC

ADT: 7509  
 ACCIDENT RATE: 0.15 CR INDEX: 0.81  
 SEVERITY RATE: 0.58 FAR INDEX: 1.08

LIGHT	WEATHER	SEVERITY CODE
L = LIGHT DN = DAWN DU = DUSK D = DARK X = UNKNOWN	C = CLEAR CL = CLOUDY R = RAIN S = SNOW/SLEET X = OTHER/UNKNOWN	○ PROPERTY DAMAGE ⊕ POSSIBLE INJURY ⊙ MINOR INJURY ⊙ SERIOUS INJURY ● FATALITY



**ANOKA COUNTY  
HIGHWAY DEPT.**

**COLLISION  
DIAGRAM**

CSAH 22 (Viking Blvd) @  
Cedar Dr  
2018 to 2022