CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

County of Anoka


State of Minnesota

Southeast Corner of Sec. 31 Township 31 Range 22

On the 9th day of April , 1962, the described corner was evidenced by a 4" square concrete monument and to perpetuate the location of said corner, at the exact location thereof, a permanent marker was placed consisting of a cast iron monument on top of broken off 4" square concrete monument

AND on the 15th day of August , 2017, said permanent marker was found flush with the surface and the ties were updated

Updated reference ties are as shown below.





12/05/17

N.A.D. 1983 Coordinates (1996 Adjustment)

County Project Coordinates	
Northing <u>132427,2296</u>	
Easting	537324.0583
Date	3/16/98

HISTORY OF GOVERNMENT CORNER

County of Anoka

State of Minnesota

Southeast Corner of Sec. 31 Township 31 Range 22

CORNER HISTORY:

October 28, 1944 - Cartwright found Concrete Monument down 0.6'±. Established ties to monument.

June 4, 1959 - N.S.P. Found 4" Square Stone Monument down 1.0'± and updated ties.

April 9, 1962 - Found 4" Square Concrete Monument with top broken off down 0.7'±. Set 3/4" Iron Pipe on north side flush with monument. Updated ties.

June 16, 1965 - Found Concrete Monument and updated ties.

June 26, 1973 - Set Cast Iron Monument flush with the surface on top of 4" Square Concrete Monument. Updated ties.

August 20, 1976 - Found Cast Iron Monument and updated ties.

August 4, 1980 - Found Cast Iron Monument and updated ties.

July 8, 1986 - Found Cast Iron Monument and updated ties.

April 18, 1990 - Found Cast Iron Monument and updated ties prior to road construction.

May 30, 1990 - Removed Cast Iron Monument prior to road construction.

August 17, 1990 - Reset Cast Iron Monument after road construction and updated ties.

October 24, 1991 - Found Cast Iron Monument and updated ties.

March 16, 1998 - Found Cast Iron Monument and established NAD 1983 (1996 Adjustment) Anoka County Project Coordinates by Static GPS methods. Updated ties.

July 15, 2010 - Found Cast Iron Monument down 0.2'± and updated ties.

January 9, 2017 - Found Cast Iron Monument down 0.2'± and verified position by VRS GPS methods. Updated ties

June 9, 2017 - Set construction ties and removed cast iron monument prior to road construction.

July 6, 2017 - Set cast iron monument flush with the surface after road construction using construction ties. Verified location of corner by Static and VRS GPS methods. Updated ties.

August 15, 2017 - Found Cast Iron Monument flush with the surface. Verified location of corner by VRS GPS methods and updated ties.